	<del>.</del>							•				
	NO. OF COPIES RECEIVED		1									
	DISTRIBUTION											
				N		CONSERVATION COMMISSION		Form C-104				
	SANTA FE	<i>∐.</i>	1		REQUES <sup>*</sup>	FOR ALLOWABLE		Supersedes Old G-104 and C				
	FILE	/_				AND		Effective 1-1-65				
	U.S.G.S.		L	AUTHORIZ	ZATION TO TR	ANSPORT OIL AND NA	TURAL GAS	•				
	LAND OFFICE			1				•				
	TRANSPORTER OIL											
	GAS	1										
	OPERATOR	1										
¥.	PRORATION OFFICE											
••	Operator		L									
	Blackwood 8											
	Address	Blackwood & Nichols Company										
				_								
	P.O. Box 1237 Durango, Colorado 81301											
	Reason(s) for filing (Check proper box)  Other (Please explain)											
	New Well			Change in Tra	insporter of:							
	Recompletion			Oil	Dry C	as J		0 2				
	Change in Ownership			Casinghead G	as Cond	ensate	1+	Inland				
						- Court		minne				
	If change of ownership give and address of previous ow											
EE.	DESCRIPTION OF WELL AND LEASE											
	Lease Name			Well No. Poo	ol Name, Including	Formation	nd of Lease	Lease No				
	Northeast Blanco	) Un	it	12 B1	anco Mesave	rde 🐃	<b>x</b> ≰ Federal ox	Ree  079082				
	Location											
	Unit Letter G	. 25	000	Feet From Th	N .	ne and2500	7 B B	E				
	Unit Letter	;		Feet From In	reL:	ne ana	eet from The					
	Line of Section 18			00	D		0 7					
	Line of Section 10		m									
			Tow	nship 30N	Range	W, NMPM,	San Jua	n County				
TU	DECICALATION OF TRA	ven					san Jua	n County				
NH.	DESIGNATION OF TRA		ORT	ER OF OIL AN	D NATURAL G	AS						
AH.	Name of Authorized Transpor	ter of	ORT	ER OF OIL AN		AS Address (Give address to u	hich approved o	copy of this form is to be sent)				
NH.	Name of Authorized Transpor Inland Corporat	ter of	<b>ORT</b>	ER OF OIL AN	D NATURAL G	AS Address (Give address to u	hich approved o	copy of this form is to be sent)				
HH.	Name of Authorized Transpor	ter of	<b>ORT</b>	ER OF OIL AN	D NATURAL G	AS Address (Give address to u	hich approved o					
NH.	Name of Authorized Transpor Inland Corporat	ter of ion ter of	ORT	ER OF OIL AN	D NATURAL G	AS Address (Give address to u  P.O. Box 1528, Address (Give address to u	hich approved o Farmingt hich approved o	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent)				
NH.	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural	ion ter of Gas	ORT	ER OF OIL AN	D NATURAL G	AS Address (Give address to u  P.O. Box 1528, Address (Give address to u	hich approved o Farmingt hich approved o Farmingto	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401				
II.	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor	ion ter of Gas	ORT	er of oil AN or Conder	D NATURAL G	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?	hich approved o Farmingt hich approved o Farmingto	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.	ter of Lion ter of Gas	ORT	er of OIL AN or Conder or pany Unit   Sec. G   18	or Dry Gas X	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?  Yes	hich approved of Farmingt hich approved of Farmingto	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is comming	ter of Lion ter of Gas	ORT	er of OIL AN or Conder or pany Unit   Sec. G   18	or Dry Gas X	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?  Yes	hich approved of Farmingt hich approved of Farmingto	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.	ter of Lion ter of Gas	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?  Yes  give commingling order nu	hich approved of Farmingt hich approved of Farmingto When When	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA	ter of Lion ter of Gas	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?  Yes  give commingling order nu	hich approved of Farmingt hich approved of Farmingto When When	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co	ter of Lion ter of Gas	ORT	er of OIL ANd or Conder or	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu	Farmingt hich approved of Farmingto When when	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA	ter of Lion ter of Gas	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528,  Address (Give address to u P.O. Box 990,  Is gas actually connected?  Yes  give commingling order nu	Farmingt hich approved of Farmingto When when	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co	cion cion ter of Gas s,	ORT	er of OIL ANd or Conder or	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu	Farmingt hich approved of Farmingto When when	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co	cion cion ter of Gas s,	ORT	er of OIL ANd or Conder or	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu	Farmington when when proved of the province of	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co	cion cion ter of Gas s,	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth	Farmington when when proved of the province of	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Resty.   Diff. Rest				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co	cion cion ter of Gas s,	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth	Farmington Farmington When Deepen Pl	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Resty.   Diff. Rest				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids qive location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR	cion cion ter of Gas s,	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth	Farmington Farmington When Deepen Pl	copy of this form is to be sent)  on, New Mexico 87401  copy of this form is to be sent)  on, New Mexico 87401  6-28-60  ag Back   Same Res'v.   Diff. Res'  B.T.D.				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids qive location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR	cion cion ter of Gas s,	ORT	or Condernghead Gas or Con	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  Cas Well  to Prod.	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent)  on, New Mexico 87401  copy of this form is to be sent)  on, New Mexico 87401  6-28-60  ag Back   Same Res'v.   Diff. Res'  B.T.D.				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commin COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR Perforations	cion cion ter of Gas s,	ORT	or Condernation of Condernatio	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  I Gas Well  to Prod.  Formation	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Res'v.   Diff. Res'   B.T.D.   Same Depth   Same Depth   Same Depth Specific Shoe				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids qive location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR	cion cion ter of Gas s,	ORT	or Condernation of Condernatio	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  Cas Well  to Prod.	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent)  on, New Mexico 87401  copy of this form is to be sent)  on, New Mexico 87401  6-28-60  ag Back   Same Res'v.   Diff. Res'  B.T.D.				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commin COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR Perforations	cion cion ter of Gas s,	ORT	or Condernation of Condernatio	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  I Gas Well  to Prod.  Formation	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Res'v.   Diff. Res'   B.T.D.   Same Depth   Same Depth   Same Depth Specific Shoe				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commin COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR Perforations	cion cion ter of Gas s,	ORT	or Condernation of Condernatio	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  I Gas Well  to Prod.  Formation	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Res'v.   Diff. Res'   B.T.D.   Same Depth   Same Depth   Same Depth Specific Shoe				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids give location of tanks.  If this production is commin COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR Perforations	cion cion ter of Gas s,	ORT	or Condernation of Condernatio	or Dry Gas X  Twp. Rge. 30N 7W  her lease or pool  I Gas Well  to Prod.  Formation	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth  Top Oil/Gas Pay	Farmington Farmington When Deepen Pl	copy of this form is to be sent) on, New Mexico 87401 copy of this form is to be sent) on, New Mexico 87401 6-28-60  ug Back   Same Res'v.   Diff. Res'   B.T.D.   Same Depth   Same Depth   Same Depth Specific Shoe				
	Name of Authorized Transpor Inland Corporat Name of Authorized Transpor El Paso Natural If well produces oil or liquids qive location of tanks.  If this production is commit COMPLETION DATA  Designate Type of Co Date Spudded  Elevations (DF, RKB, RT, GR	cion cion ter of Gas s,	ORT	or Conder	or Dry Gas X  Twp. Rge.  30N 7W  her lease or pool	AS  Address (Give address to u P.O. Box 1528, Address (Give address to u P.O. Box 990, Is gas actually connected? Yes give commingling order nu New Well Workover Total Depth	Farmington Farmington When Deepen Pl	copy of this form is to be sent)  on, New Mexico 8740  copy of this form is to be sent)  on, New Mexico 8740  6-28-60  ag Back   Same Res'v.   Diff. Res				

(Test must be after recovery of total volume of load oil and must be equal able for this depth or be for full 24 hours) V. TEST DATA AND REQUEST FOR ALLOWABLE OIL WELL

bdie i liei Mew Cit Mail 10 1dire	200 01 1001	Trouboning Montes (1 100) par	RILLIVED
Length of Test	Tubing Pressure	Casing Pressure	Chake Size
Actual Prod. During Test	Oil-Bbis.	Water - Bbls.	OIL CON. COM.
GAS WELL			DIST. 3

Actual Prod. Test-MCF/D Length of Test Bbls. Condensate/MMCF Gravity of Condensate Casing Pressure (Shut-in) Testing Method (pitot, back pr.) Tubing Pressure (Shut-in) Choke Size

## VI. CERTIFICATE OF COMPLIANCE

I hereby certify that the rules and regulations of the Oil Conservation Commission have been complied with and that the information given above is true and complete to the best of my knowledge and belief.

⊃=DeLasso Loos (Signature)

District Manager

(Title)

6-24-74 (Date) OIL CONSERVATION COMMISSION

HM 2.5/1974 Allelis SUPERVISOR DIST. #3

TITLE

This form is to be filed in compliance with RULE 1104.

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition.