#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

APPLICATION FOR PERMIT TO DRILL OR REENTER

FORM APPROVED OMB No 1004-0136 Expires January 31, 2004

5. Lease Serial No

NMSF-**Ø**078770 6. If Indian, Allottee or Tribe Name

						1200	anemen				
la. Type of Work	☑ DRILL		☐ REENTER	Farmington Field Office			7. If Unit o	r CA Agreeme	nt, Name an	d No.	
• •			_		,			Rosa Unit			
	الاستان ال	☐ Gas Well	Пол	<b>5</b> 1.0				8. Lease Na	ame and Well N	o.	
1b. Type of Well:			U Otner	- KI 3	ingle Zone	Multipl	e Zone	257/			
2 Name of Opera	tor oduction Com	nany II.C						9. API We	-039-3	30390	)
3a, Address	oddellon Com	parry, LLC		3b. Phone No	o. (include ar	rea code)			d Pool, or Expl		
P.O. Box 64	0 Aztec, NM 8	37410		(505)	634-4208	·			- Mesaverde	<b>5</b>	with a
	<del></del>		accordance with any	•				11. Sec., T.,	R., M., or Blk	and Survey	or Area
At surface	1285' FNL	& 1890' FWL	·	•	,						
At proposed pro	od. zone						ĺ	C Section	n 27, 31N R.	5W	
14. Distance in mile	s and direction f	from nearest tow	n or post office*					12. County		13. S	tate
approximatel	v 34 miles nor	theast of Bland	co, New Mexico				1	Rio Ar	тiba	1	NM
15. Distance from pr	<del></del>			16. No. of	Acres in lease	e T	17. Spacing		ed to this well		
location to neare	st							,		<b>MAY 28</b>	'08
(Also to nearest		fany) 12	285'	2,566	0.00	ĺ	320	0 (W/2)		ONS. D	
18. Distance from pr	oposed location			19. Propose				IA Bond No.		UNJ	
to nearest well, d		ed,				ļ			n	IST. 3	
applied for, on th	•	2100		3,51	B'	L	UŢĐ	47		20110	
21. Elevations (Sho	w whether DF,	KDB, RT, GL,	etc.)	22. Approx	imate date v	work will sta	rt*	23. Estimat	ed duration		
6,569' GR				Sprin	g 2008			1 month			
				24. Atta	chments						
The following, compl	eted in accordar	nce with the requ	uirements of Onshor	e Oil and Gas	Order No.1,	shall be attac	hed to this	form:			
Well plat certified	by a registered	surveyor.			4. Bond	to cover the	operations	unless cover	ed by an exist	ing bond or	ı file (see
2. A Drilling Plan.	, ,	•				20 above).			-		
3. A Surface Use Pl				Lands, the	-	tor certificat		4' 4/-			1.1
SUPO shall be fi	led with the ap	propriate Fores	st Service Office).			otner site sp rized officer		mation and/o	or plans as ma	y be requir	ed by the
25. Signature	1/	-		Name	(Printed/Type	ed)			Date	:	
low	ey Au	2a -			Larry Higgir	ns				0-4-	-07
Title	,, -9	, ,									
Drilling COM											
Approved by (Signati	D/110	ankee	200	Name	(Printed/Type	ed)			Date	5/2	7/08
Title	4	17=11		Office	FE	<u>-0</u>					
Application approval	does not warran	it or certify that	the applicant holds le	egal or equital	ble title to the	ose rights in t	he subject le	ease which wo	ould entitle the	applicant to	conduct
operations thereon. Conditions of approve	al, 1f any, are att	ached.									
Title 18 U.S.C. Section States any false, fictit							willfully to	make to any	department or a	igency of th	e United
*(Instructions on rever	rse)						<del>/                                    </del>				
							/				

Williams Exploration and Production Company, LLC, proposes to drill a well to develop the Basin Fruitland Coal Formation at the above described location in accordance with the attached drilling and surface use plans

The surface is under jurisdiction of the Carson National Forest, Jicarilla Ranger District

PRIOR
This location has been archaeologically surveyed La Plata Archaeological Consultants. Copies of their

An access road of 2,750 feet is needed, if this well is drilled prior to the proposed Rosa Unit No. 186B. The Rosa Unit No. 257A and the Rosa Unit No. 186B are on a twinned location.

A pipeline tie of 2857.2 feet would be required for this location. Williams Field Services has filed a pipeline route plan for the associated pipeline. The pipeline will be owned and operated by Williams Field Services.

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS JUN 0 3 2008 (

This action is subject to technical and procedural review pursuant to 43 CFR 3165.3

DRILLING OPERATIONS AUTHORIZED ARE SUBJECT TO COMPLIANCE WITH ATTACHED "GENERAL REQUIREMENTS".

District I PO Box 1980, Hobbs, NM 88241-1980 District II PO Drawer DD. Artesia, NM 88211-0719

District III 1000 Rio Brazos Rd., Aztec, NM 87410

District IV PO Box 2088, Santa Fe, NM 87504-2088

State of New Mexico Energy, Minerals & Natural Resources Department

Form C-102 Revised February 21, 1994 Instructions on back Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

OIL CONSERVATION DIVISION PO Box 2088 OCT 4 2007 Santa Fe, NM 87504-2088

Bureau of Land Management Farmington Field Office


RECES

AMENDED REPORT

#### WELL LOCATION AND ACREAGE DEDICATION PLAT

'API Number				*Pool Coo							
30.039.30390 71629					BASIN FRUITLAND COAL						
Property Code					Property Name				*Well Number		
17033					ROSA UNIT				257A		
'OGRID No.					•	*Operator Name				*Elevation	
120782 WILL:					AMS PRODUCTION COMPANY					6569	
	<sup>10</sup> Surface Location										
UL or lot no.	Section	Township	Range	Lat Idn	Feet from the	North/South line	Feet from the	East/Wes	st line	County	
С	27	31N	5W		1285	NORTH	1890	WEST RIO ARRIBA			
	<sup>11</sup> Bottom Hole Location If Different From Surface										
UL or lot no	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/Wes	st line	County	
<sup>12</sup> Deducated Acres  320.0 Acres - (W/2)				<sup>13</sup> Jaint or Infill	<sup>34</sup> Consolidation Code	<sup>25</sup> Onder No.					

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



Office	State of New Mexic		Form C-103
District I	Energy, Minerals and Natural	Resources	May 27, 2004  L API NO
1625 N. French Dr., Hobbs, NM 88240 District II	OIL CONSERVATION D	2	50039.30390
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis	l 5 ir	dicate Type of Lease FEDERAL X  STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 8750	. <b>_</b>	STATE FEE atte Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			78770
SUNDRY NOT	CES AND REPORTS ON WELLS		ease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG I CATION FOR PERMIT" (FORM C-101) FOR S	1 1011	a Unit
PROPOSALS.)	Gas Well 🛛 Other	KOS	Vell Number 257A
Type of Well: Oil Well     Name of Operator	Gas Well 💹 Other		GRID Number 120782
Williams Production Company, LL	.C		
3. Address of Operator P.O. Box 640 Aztec, NM 87410		Blan	co Mesaverde
4. Well Location			
	rom the north line and 1890 feet from t	he west line	
Section 27 Township	31N Range 5W 11. Elevation (Show whether DR, RI	NMPM	County Rio Arriba
	11. Elevation (Show whether DR, RI 6,569' GR	CB, K1, GK, etc.)	
Pit or Below-grade Tank Application 🛛 o			
Pit typereserveDepth to Groundwat	er>100'_Distance from nearest fresh water	well_>1,000'_ Distance fro	m nearest surface water>1,000'
Pit Liner Thickness: 12 mil Below	Grade Tank: Volume bb	s; Construction Material	
12. Check A	Appropriate Box to Indicate Natu	ire of Notice, Repo	rt or Other Data
NOTICE OF IN	TENTION TO:	SUBSEQ	JENT REPORT OF:
PERFORM REMEDIAL WORK		EMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON  PULL OR ALTER CASING	I	OMMENCE DRILLING	OPNS. PANDA
PULL OR ALTER CASING	MOLTIFLE COMPL	ASING/CEMENT JOB	Ш
OTHER:		THER:	
1 {   } escribe proposed or comp			
			pertinent dates, including estimated date ellbore diagram of proposed completion
			pertinent dates, including estimated date ellbore diagram of proposed completion
of starting any proposed wo			
of starting any proposed wo			
of starting any proposed we or recompletion.  Drilling/Completion pit to be located to the starting any proposed we or recompletion.	ork). SEE RULE 1103. For Multiple (	Completions: Attach w	ellbore diagram of proposed completion  -use drilling and completion to avoid
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi	ork). SEE RULE 1103. For Multiple ( ed approximately 50 to 75 feet from t will be considered out of service o	Completions: Attach with well head. Pit multinge production tubin	ellbore diagram of proposed completion  -use drilling and completion to avoid
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi	ork). SEE RULE 1103. For Multiple (	Completions: Attach with well head. Pit multinge production tubin	ellbore diagram of proposed completion  -use drilling and completion to avoid
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi	ork). SEE RULE 1103. For Multiple ( ed approximately 50 to 75 feet from t will be considered out of service o	Completions: Attach with well head. Pit multinge production tubin	ellbore diagram of proposed completion  -use drilling and completion to avoid
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi	ork). SEE RULE 1103. For Multiple ( ed approximately 50 to 75 feet from t will be considered out of service o	Completions: Attach with well head. Pit multinge production tubin	ellbore diagram of proposed completion  -use drilling and completion to avoid
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi operated and closed in accordan	ork). SEE RULE 1103. For Multiple ( ed approximately 50 to 75 feet from t will be considered out of service o ce with NMOCD guidelines and Wil	Completions: Attach was well head. Pit multinge production tubin liams' procedures.	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi operated and closed in accordant.  I hereby certify that the information	ork). SEE RULE 1103. For Multiple ( ed approximately 50 to 75 feet from t will be considered out of service o ce with NMOCD guidelines and Wil	completions: Attach well head. Pit multince production tubin liams' procedures.	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi operated and closed in accordant.  I hereby certify that the information	ed approximately 50 to 75 feet from twill be considered out of service of the with NMOCD guidelines and Will above is true and complete to the best closed according to NMOCD guidelines [2], a	completions: Attach well head. Pit multince production tubin liams' procedures.	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,
of starting any proposed we or recompletion.  Drilling/Completion pit to be local additional site disturbance and pi operated and closed in accordant or accordant or the start of the star	ed approximately 50 to 75 feet from twill be considered out of service of the with NMOCD guidelines and Will above is true and complete to the best closed according to NMOCD guidelines \( \text{\tex	completions: Attach well head. Pit multionce production tubin liams' procedures.  of my knowledge and begeneral permit  or an (a	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,  relief. I further certify that any pit or below- ttached) alternative OCD-approved plan
of starting any proposed we or recompletion.  Drilling/Completion pit to be local additional site disturbance and pi operated and closed in accordant or accordant library certify that the information grade tank has been/will be constructed or	ed approximately 50 to 75 feet from t will be considered out of service of the with NMOCD guidelines and Will above is true and complete to the best closed according to NMOCD guidelines and the closed according to NMOCD guidelines and the closed according to NMOCD guidelines are according to NMOCD guidelines ar	completions: Attach we well head. Pit multionce production tubinitiams' procedures.  of my knowledge and begeneral permit or an (a prilling illiams.com	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,  relief. I further certify that any pit or below- ttached) alternative OCD-approved plan .  COMDATE
of starting any proposed we or recompletion.  Drilling/Completion pit to be locat additional site disturbance and pi operated and closed in accordant or significant the information grade tank has been/will be constructed or SIGNATURE	ed approximately 50 to 75 feet from t will be considered out of service of the with NMOCD guidelines and Will above is true and complete to the best closed according to NMOCD guidelines and the closed according to NMOCD guidelines and the closed according to NMOCD guidelines are according to NMOCD guidelines ar	completions: Attach well head. Pit multionce production tubin liams' procedures.  of my knowledge and begeneral permit  or an (a	ellbore diagram of proposed completion  -use drilling and completion to avoid g set. Pit to be constructed,  relief. I further certify that any pit or below- ttached) alternative OCD-approved plan   COM DATE 10-4-3-7  one No. (505) 634-4208  Inspector,



# **WILLIAMS PRODUCTION COMPANY**

## **Operations Plan**

(Note: This procedure will be adjusted on site based upon actual conditions)

DATE:

5/14/2007

**WELLNAME:** 

Rosa Unit #257A

Rio Arriba, NM

FIELD:

Basin Fruitland Coal

**BH LOCATION:** 

NENW Sec 27-T31N-5W

**SURFACE:** 

FOREST

ELEVATION:

6,569' GR

MINERALS:

FED

**TOTAL DEPTH:** 

3,518'

LEASE #

SF-078770

I. GEOLOGY:

Surface formation - San Jose

#### A. FORMATION TOPS: (KB)

NAME	MD	NAME	MD	
San Jose	Surface	Top Coal	3,323	
Nacimiento	1,488	Bottom Coal	3,418	
Ojo Alamo	2,723	Pictured Cliffs	3,418	
Kirtland	2,833	TD	3,518	
Fruitland	3,203			

- B. <u>LOGGING PROGRAM:</u> SDR from TD to Intermediate casing. DSN from TD to surface casing.
- C. <u>NATURAL GAUGES</u>: Gauge any noticeable increases in gas flow. Record all gauges in Tour book and on morning reports.
- D. MUD LOGGING PRORAM: Mud logger will be on location at drill out below 7" casing to TD.

#### II. DRILLING

- A. <u>MUD PROGRAM</u>: Clear water with benex to 7" casing point. Treat for lost circulation as necessary. Expect 100% returns prior to cementing. Notify Engineering of any mud losses. If coal is detected before 3,303', <u>DO NOT</u> drill deeper until Engineering is contacted.
- B. DRILLING FLUID: Coal section will be drilled with Fruitland Coal water.

C. <u>BOP TESTING:</u> While drill pipe is in use, the pipe rams and the blind rams will be function tested once each trip. The anticipated reservoir is expected to be less than 1300 psi, so the BOPE will be tested to 250 psi (Low) for 5 minutes and 1500 psi (High) for 10 minutes. Utilize a BOPE Testing Unit with a recording chart and appropriate test plug for testing. The drum brakes will be inspected and tested each tour. All tests and inspections will be recorded in the tour book as to time and results.

#### III. MATERIALS

#### A. CASING PROGRAM:

CASING TYPE	OH SIZE (IN)	DEPTH (MD) (FT)	CASING SIZE (IN)	WEIGHT(LB) GRADE
Surface	12 1/4	300	9 5/8	36 K-55
Intermediate	8 3/4	3,303	7	20 K-55
Liner	6 1/4	3,203 3,418	5 1/2	15.5 J-55

#### **B. FLOAT EQUIPMENT:**

- 1. <u>SURFACE CASING:</u> 9-5/8" notched regular pattern guide shoe. Run (1) standard centralizer on each of the bottom (4) joints of Surface Casing.
- 2. INTERMEDIATE CASING: 7" cement nose guide shoe with a self-fill insert float. Place float collar one joint above the shoe. Install (1) Turbulent centralizer on each of the bottom (3) joints and one standard centralizer every (3) joints to 2,500 ft. Run (1) Turbulent centralizer at 2,700 ft., 2,500 ft., 2,300ft., 2,000ft., 1,500 ft., and 1,000 ft. (NTL-FRA 90-1).
- 3. <u>PRODUCTION LINER / CASING:</u> 5-1/2" whirler type cement nose guide shoe with a latch collar on top of 20' bottom joint. Place centralizers as needed across selected production intervals.

#### C. CEMENTING:

(Note: Volumes may be adjusted onsite due to actual conditions)

- 1. SURFACE: Use 160 sx (224 cu.ft.) of "Type III" with 2% CaCl<sub>2</sub> and 1/4# of cello-flake/sk (Yield = 1.41 cu.ft./sk, Weight = 14.5 #/gal.). Use 120% excess to circulate the surface. WOC 12 hours. Total volume = 206 cu.ft. Test to 1500#.
- 2. INTERMEDIATE: Lead 410 sx (853 cu.ft.) of "Type III" 65/35 poz with 8% gel, 1% CaCl<sub>2</sub> and 1/4# cello-flake/sk (Yield = 2.09 cu.ft./sk, Weight = 12.1 #/gal.). Tail 50 sx (70cu.ft.) of "Type III" with 1/4# cello-flake/sk, and 1% CaCl<sub>2</sub> (Yield = 1.4 cu.ft./sk, Weight = 14.5#/gal.). Use 100% excess in Lead Slurry to circulate to surface. No excess in Tail Slurry. Total volume = 923 cu.ft. Bump Plug to 1,500 psi. Notify engineering if cement is not circulated to surface.
- 3. PRODUCTION LINER: Open hole completion. No cement.

#### IV. COMPLETION

#### A. PRESSURE TEST

1. Pressure test 7" casing to 1500# for 15 minutes as per state regulations.

# B. STIMULATION

1. <u>Cavitate well</u> with reciprocation and rotation. Surge wells with water and air and then flow back. Cavitate for 2 to 3 weeks. Maximum pressure not expected to exceed 2,000 psi.

# C. RUNNING TUBING

1. <u>Fruitland Coal:</u> Run 2-7/8", 6.5#, J-55, EUE tubing with a SN on top of bottom joint. Land tubing approximately 50' above TD.

Gary Sizemofe
Sr. Drilling Engineer

Rosa #257A Op.doc

#### GENERAL ROSA DRILLING PLAN

#### Rosa Unit boundries:

T31N, R4W: all except sections 32-36 T31N, R5W: all except sections 1 & 2

T31N, R6W: all except sections 6,7,18,20, & 27-36

T32N, R6W: sections 32-36

FORMATION	LITHOLOGY	WATER	GAS	OIL/COND	OVER-PRES	LOST CIRC
Nacimiento	Interbedded shales, siltstones and sandstones	Possible	Possible	No	No	No
Ojo Alamo	Sandstone and conglomerates with lenses of shale	Fresh	No	No	No	No
Kirtland	Shale W/interbedded sandstones	No	Possible	No	No	No
Fruitland	Inter, SS, SiltSt, SH &Coals w/carb, SS, SiltSt, SH	Yes	Yes	No	Possible	Possible
Pictured Cliffs	Massive Sandstone w/thin interbedded shales	Possible	Yes	Possible	No	Possible
Lewis	Shale within interbedded sandstones and siltstones	No	Possible	No	No	No
Cliff House	Transgressive sandstones	Possible	Yes	No	No	No
Menefee	Sandstones, carb shales and coal	Possible	Yes	No	No	No
	Regressive coastal barrier sandstone	Possible	Yes	Possible	No	Yes
Mancos	Marine shale and interbedded sandstone	No	Possible	Possible	No	Possible
Upr Dadota	Marine sand and shales	No	Yes	Possible	No	Possible
Lwr Dakota	Fluvial sands, shales, & coal	Possible	Yes	Possible	No	Possible


## DRILLING

#### Potential Hazards:

- 1. There are no overpressured zones expected in this well.
- 2. No H2S zones will be penetrated while drilling this well.

#### Mud System:

- Surface The surface hole will be drilled with a low-solids, non-dispersed system with starch and lost circulation material as needed. Expected mud weights will be in the 8.4 to 9.0 lb per gal range. Viscosities will be in the 30 to 60 sec/qrt range as needed to remove drill cuttings.
- 2. Intermediate The intermediate hole will be drilled with clear water and Benex to TD where the well will be mudded up to log and run casing. The mud system will be low-solids, non-dispersed with mud weights in the 9 to 10 lb per gal range as needed to control the well. Viscosities will be in the 45 to 55 range as needed to support any weight material. The weight material will consist of Barite.
  - 3. Production The well will be drilled using air from the intermediate casing point to TD. For Fruitland Coal wells, the coal section will be drilled with air/mist.



# Well Control Equipment Schematic for 2M Service

Attachment to Drilling Technical Program

# Exhibit #1 Typical BOP setup

