

**UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT**

RECEIVED

AUG 29 2008

Sundry Notices and Reports on Wells

Bureau of Land Management
Farmington Field Office

1. **Type of Well**
GAS

2. **Name of Operator**
CDX RIO, LLC

3. **Address & Phone No. of Operator**

2010 Afton Place, Farmington, New Mexico 87401 (505) 326-3003

4. **Location of Well, Footage, Sec., T, R, M**
1900' FSL, 2300' FEL, Sec. 15, T-26-N, R-5-W, NMPM

DHC-2151az

5. **Lease Number**
Jicarilla Contract 109
6. **If Indian, All. or**
Tribe Name
Jicarilla Apache
7. **Unit Agreement Name**

8. **Well Name & Number**

Jicarilla B #3M
9. **API Well No.**

30-039-29638
10. **Field and Pool**

Blanco MV/Basin DK
11. **County and State**

Rio Arriba Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment <input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion <input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging <input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair <input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing <input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other Request for long term temporary abandonment

13. Describe Proposed or Completed Operations

This sundry serves as a request for long term temporary abandonment of the subject well until the pipeline issues between The Jicarilla Apache Tribe and Williams Field Services have been resolved. CDX Rio, LLC requests this temporary abandonment for one year. The contract between the Jicarilla Apache Tribe and Williams Field Services is to expire on August 31, 2008. At this time, CDX Rio, LLC is not aware that these issues have been resolved. A cast iron bridge plug was set in the well on August 20, 2007. The cast iron bridge plug was tested on September 19, 2007 to 1000 psi/20 minutes, the test was OK. When these pipeline issues have been resolved, an intent sundry will be submitted to sidetrack and complete the well or plug and abandon the well.

**RCVD SEP 3 '08
OIL CONS. DIV.
DIST. 3**

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Olthmann Title Agent Date 8-26-08

(This space for Federal or State Office use)

APPROVED BY Original Signed: Stephen Mason Title _____ Date SEP 02 2008
CONDITION OF APPROVAL, if any:

NMOC