

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SEP 15 2008

FORM APPROVED
OMB No 1004-0135
Expires July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

Abandoned well. Use Form 3160-3 (APD) for such proposals.

5 Lease Serial No

NMSF 078510

6 If Indian, Allottee or tribe Name

7 If Unit or CA/Agreement, Name and/or No

SUBMIT IN TRIPLICATE – Other instructions on reverse side

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

8. Well Name and No

Jacquez 2

2 Name of Operator

BP America Production Company Attn: Cherry Hlava

9 API Well No

30-045-27522

3a Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No (include area code)

281-366-4081

10 Field and Pool, or Exploratory Area

Basin Fruitland Coal

4 Location of Well (Footage, Sec., T., R., M. or Survey Description)

1370' FNL & 1295' FEL SEC 6 T31N R08W SENE

11 County or Parish, State

San Juan County, New Mexico

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☒ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☐ Other

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

9/2/08 RIG UP SCHLUMBERGER; PUMP 1,000 gal. 15 % HCL ACID DOWN TUBING. FLUSHED USING 5 BBLs. OF 2 % KCL WATER. RIG UP; PUMP 500 gal. ACID DOWN CASING. FLUSHED WITH 5 bbls. 2 % KCL WATER. RIG DOWN SCHLUMBERGER. SHUT WELL IN TO LET ACID SOAK ON PERFORATIONS. SECURE WELL. RIG DN MOVE OFF

RCVD SEP 18 '08

OIL CONS. DIV.

DIST. 3

14 I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title **Regulatory Analyst**

Signature *Cherry Hlava*

Date **09/09/2008**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by	Title	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant or Certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon	Office	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ACCEPTED FOR RECORD

SEP 16 2008

NMOCD

FARMINGTON FIELD OFFICE