

Bill Richardson

Governor

Joanna Prukop
Cabinet Secretary
Reese Fullerton
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



October 7, 2008

Cherry Hlava B P America PO Box 3092 Houston TX, 77253

Re: Mudge Gas Com B 001M, P-11-31N-11W, API # 30-045-32735

Dear Ms. Hlava:

The 2008 Bradenhead test on the above well indicates a failure. In order to comply with Rule 108, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before January 8, 2009. Bradenhead psi of 502 was reported 7-17-08.

With your sundry please attach a copy of the last two tests, a current wellbore schematic including formation and cement tops. Indicate the method used to determine the cement top; provide gas analysis from both the production and intermediate casing.

Reference: RBDMS CTP0827553905 on future correspondence.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Kelly G. Roberts

Deputy Oil & Gas Inspector

District III-Aztec

CC: Well File