Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIORS BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. 701-08-550 14-0011

6. If Indian, Allottee or Tribe Name Jicarilla Apache Nation

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an wanage of

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. N/A 1. Type of Well 8. Well Name and No. Los Indios 3-F - 1 Oil Well **✓** Gas Well Other 2. Name of Operator Jicarilla Apache Energy Corporation 9. API Well No. 30-039-25142 3a. Address P.O. box 710, Dulce, New Mexico 87528 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area Mancos Shale 575-759-3224 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SENW Sect. 3, T 27N, R 1W 11. Country or Parish, State New Mexico 12 CHECK THE APPROPRIATE ROY(ES) TO INDICATE NATI DE OF NOTICE DEPORT OF OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	Reclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	Recomplete	Other
	Change Plans	Plug and Abandon	Temporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Repairs to the wellhead-casing valves, master valves, separator, and pipelines on location recompleted. Well placed on line January 25, 2008, 1:00 PM Mountain Standard Time.

RCVD OCT 30 '08

OIL CONS. DIV.

DIST. 3

e Production Supervisor	
e 10/09/2008	ASSISTED FOD STAND
L OD CTATE OFFICE	CHOC
L OR STATE OFFICE	E USE COT 2 0 2008
1	
Title	PARAMETON PELL OFFICE
Office	in Su
	L OR STATE OFFIC

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.