

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

NOV 24 2008 FORM APPROVED
OMB No 1004-0135
Expires July 31, 2010

Lease Serial Number
Farmington Field Office SF - 078095

6 If Indian, Allottee or tribe Name

7 If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

8 Well Name and No.

Case B 21

9 API Well No.

30-045-27777

10 Field and Pool, or Exploratory Area

Basin Fruitland Coal

11 County or Parish, State

San Juan County, New Mexico

1 Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2 Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

4 Location of Well (Footage, Sec., T., R., M., or Survey Description)

1670' FNL & 1170' FEL SEC 18 T31N & R11W, SENE

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☒ Other downsize Tbg from
2 3/8" to 1 1/2"

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof
If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

11/4/08 RU AWS 825. Pressure reading 325 psi on 5.5" CSG. Bleed DN through 3" line. ND WH; NU BOP. TIH; tag @2965'.

11/5/08 Clean out from 2966' to 2976' PBD. Run sweeps. Start pulling 2 3/8" tbg.

**11/6/08 Pull & lay down 2 3/8" tbg. TIH land 1 1/4"; 2.33#; J-55 tbg. @2785'. Well head 1500 psi; hold; blow through check for 30 mins. Pmp 3 bbls
2% KCL DN 1 1/4" tbg, drop ball & pmp off check @1400 psi.**

11/11/08 Restored to production

RCVD NOV 25 '08

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title **Regulatory Analyst**

**OIL CONS. DIV.
DIST. 3**

Signature

Cherry Hlava

Date **11/17/08**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or
Certify that the applicant holds legal or equitable title to those rights in the
subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States
any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD

NMOCD

NOV 25 2008

FARMINGTON FIELD OFFICE