

(August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
Abandoned well. Use Form 3160-3 (APD) for such proposals.*

FORM APPROVED
OMB No 1004-0135
Expires July 31, 2010

5. Lease Serial No

SF - 078904

6. If Indian, Allottee or tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side

RECEIVED

CA/Agreement, Name and/or No

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

MAR 04 2009

Well Name and No.

GCU 230E

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

Bureau of Land Management
Farmington Field Office

30-045-26010

3a Address

P.O. Box 3092 Houston, TX 77253

3b Phone No. (include area code)

281-366-4081

10. Field and Pool, or Exploratory Area

Simpson Gallup

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

790' FSL & 1060' FWL SEC 23 T28N R12W

11. County or Parish, State

San Juan County, New Mexico

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☒ Recomplete

☐ Water Disposal

☐ Water shut-Off

☐ Well Integrity

☒ Other PMP CHNG
Restored to Production

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleation in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

JANUARY '09 COMPLIANCE WELL

2/16/09 TIH w/Baker & PMP 210 gal of parfinn solvent in tbg & RDMO Baker.

2/17/09 TIH press test tbg to 500 psi; held OK. TOH w/rods & pmp. TIH w/ new 2" x 1-1/4"x14"x16' pmp.

2/18/09 TIH w/Rods; PU polish rod & seat pmp. Fill hole w/2% KCL & pressure test to 500 psi w/rig pmp. RDMO AWS 442

2/19/09 Well produced 4.3 mcf/d

RCUD MAR 9 '09

14. I hereby certify that the foregoing is true and correct
Name (Printed/typed)

Cherry Hlava

Title **Regulatory Analyst**

OIL CONS. DIV.
DIST. 3

Signature *Cherry Hlava*

Date **02/26/2009**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or
Certify that the applicant holds legal or equitable title to those rights in the
subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States
any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

ACCEPTED FOR RECORD

MAR 06 2009

NMOCD

FARMINGTON FIELD OFFICE

TY

SM