

RECEIVED

MAY 01 2009

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS
 Do not use this form for proposals to drill or to re-enter an
 Abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM APPROVED
OMB No. 1004-0135
Expires July 31, 20105. Lease Serial No. **076337**
SF 078237

6. If Indian, Allottee or tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

BP America Production Company Attn: Cherry Hlava

3a. Address

P.O. Box 3092 Houston, TX 77253

3b. Phone No. (include area code)

281-366-4081

8. Well Name and No.

Rochelle Gas Com #1

9. API Well No.

30-045-11634

10. Field and Pool, or Exploratory Area

Blanco Pictured Cliffs

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

880' FSL & 870' FEL Sec. 4 T29N, R09W SESE

11. County or Parish, State

San Juan County, New Mexico

12 CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OR NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☒ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Water Disposal☐ Water shut-Off☐ Well Integrity☐ Other**RCVD MAY 5 '09****OIL CONS. DIV.****DIST. 3**

13 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.

APRIL 2009 COMPLIANCE WELL**4/22/09** RU AWS 556 SI CSG pressure 80 psi. Blw DN.**4/23/09** TOH lay DN104 joints 1-1/4 line pipe**4/24/09** TIH set CIBP @2188' Load & test CSG to 500 psi - O K RU Schlumberger & run CBL 2188' - surface - showing good bond to surface. 1st plug - TIH pmp 28 sxs Class G Cmt 2188' - 1830'; Density 15.80 ppg; Yield 1.150 fcu/sk. 2nd plug - TIH pmp 33 sxs class G Cmt 1326' - 903'; Density 15.80 ppg; Yield 1.150 cuft/sk**4/27/09** 3rd plug - pmp 24 sxs Class G cmt 290' to surface; Density 15.80 ppg; Yield 1.150 cuft/sk. ND BOP, Cut off well head, top off with 1/4 bbls cement, Ray Espanosa (BLM) approved the top off of cement. Install P&A marker. Rig DN move off location.

14. I hereby certify that the foregoing is true and correct

Name (Printed/typed)

Cherry Hlava

Title Regulatory Analyst

Signature *Cherry Hlava*

Date 04/30/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

ACCEPTED FOR RECORD

Approved by

Title

Date

MAY 04 2009

Conditions of approval, if any, are attached. Approval of this notice does not warrant or
 Certify that the applicant holds legal or equitable title to those rights in the
 subject lease which would entitle the applicant to conduct operations thereon.

Office

FARMINGTON FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

8/5/12