Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No.

NN	1NM3695	2	

SUNDKT N	Offices and Reports on Wells	
Do not use this	form for proposals to drill or to re-enter an	
abandoned well.	Use form 3160-3 (APD) for such proposals.	

aba	ndoned wel	ll. Use form 3160-3 (API	D) for such p	roposals.		6. If Indian, Allottee o	or Tribe Name
SUI	BMIT IN TRII	PLICATE - Other instruc	tions on rev	erse side.	-	7. If Unit or CA/Agree	ement, Name and/or No
1. Type of Well Oll Well Gas Well Other Contact: JOHN C ALEXANDER DUGAN PRODUCTION CORPORATIONALE: johncalexander@duganproduction.com					8. Well Name and No. FLO JO 93		
					 n	9. API Well No. 30-045-34517-00-X1	
3a. Address 3b. Phone No.				o. (include area		10. Field and Pool, or Exploratory	
FARMINGTON, NM 87499						BASIN FRUITLA	AND COAL
4. Location of Well (1	4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	and State
Sec 1 T23N R11W NWNW 990FNL 990FWL 36.25998 N Lat, 107.96040 W Lon					SAN JUAN COUNTY, NM		
12. C	HECK APPR	ROPRIATE BOX(ES) TO) INDICATE	NATURE	OF NOTICE, R	LEPORT, OR OTHER	R DATA
TYPE OF SUBM	ISSION			TYF	PE OF ACTION		
☐ Notice of Intent		☐ Acidize	□ Dee	epen	□ Produ	ction (Start/Resume)	☐ Water Shut-Off
_		☐ Alter Casing	□ Fra	cture Treat	□ Reclar	mation	☐ Well Integrity
Subsequent Rep		☐ Casing Repair	_	v Constructio	_		Other Drilling Operations
Final Abandonm	ent Notice	☐ Change Plans	_	g and Abando	_	orarily Abandon	Drining Operations
- U			☐ Convert to Injection ☐ Plug Back		□ Water	Disposal	
13. Describe Proposed or If the proposal is to do Attach the Bond unde following completion testing has been completermined that the si	eepen directiona or which the wor of the involved oleted. Final Ab te is ready for fi	cration (clearly state all pertineration (clearly state all pertineratily or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be filmal inspection.)	give subsurface the Bond No. o sults in a multip ted only after all	e locations and in file with BLN le completion of requirements, i	measured and true A/BIA. Required so recompletion in including reclamat	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed,	filed within 30 days 60-4 shall be filed once
13. Describe Proposed or If the proposal is to do Attach the Bond under following completion testing has been completed that the significant properties of the properties of the proposed of t	eepen directions which the wor of the involved oleted. Final Abte is ready for fing to 3500 pm 913'-938' vm	ration (clearly state all pertiner ally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be file	give subsurface the Bond No. of sults in a multipled only after all an GR-CCL-C	e locations and in file with BLN le completion of requirements, in the logs. Pe	measured and true M/BIA. Required so recompletion in including reclamater for the format (8/21/08)	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, 3) RCVD JU	nent markers and zones. filed within 30 days to 4 shall be filed once and the operator has
13. Describe Proposed or If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si Pressure test cas Fruitland Coal fro	eepen directions which the wor of the involved oleted. Final Abte is ready for fing to 3500 pm 913'-938' vm	cration (clearly state all pertinerally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be fil nal inspection.) psig for 30 mins, held. Ruw/4 spf (total 25', 100 hole	give subsurface the Bond No. of sults in a multipled only after all an GR-CCL-C	e locations and in file with BLN le completion of requirements, in the logs. Pe	measured and true M/BIA. Required so recompletion in including reclamater for the format (8/21/08)	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has L 7 '09
13. Describe Proposed or If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si Pressure test cas Fruitland Coal fro	eepen directions which the wor of the involved oleted. Final Abte is ready for fing to 3500 pm 913'-938' vm	cration (clearly state all pertinerally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be fil nal inspection.) psig for 30 mins, held. Ruw/4 spf (total 25', 100 hole	give subsurface the Bond No. of sults in a multipled only after all an GR-CCL-C	e locations and in file with BLN le completion of requirements, in the logs. Pe	measured and true M/BIA. Required so recompletion in including reclamater for the format (8/21/08)	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, 3) RCVD JU	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has L 7 '09
13. Describe Proposed or If the proposal is to do Attach the Bond under following completion testing has been completed that the significant properties of the properties of the proposed of t	eepen directions or which the word of the involved oleted. Final Abte is ready for fing to 3500 pm 913'-938' vals fluid; 93,50 the foregoing is	cration (clearly state all pertinerally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be fill nal inspection.) usig for 30 mins, held. Rull w/4 spf (total 25', 100 hole 00# 20/40 sand (7/1/09).	give subsurface the Bond No. o sults in a multip ed only after all in GR-CCL-C es). Pump 25	locations and in file with BLM le completion or requirements, in ML logs. Per solution of the	measured and true M/BIA. Required so measured and true M/BIA. Required so recompletion in including reclamate reforate (8/21/08 HCL (7/1/09).	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI OIL CONS DIST.	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has
13. Describe Proposed or If the proposal is to de Attach the Bond unde following completion testing has been comp determined that the si Pressure test cas Fruitland Coal fro Frac w/52,700 ga	the foregoing is	true and correct. Electronic Submission #	give subsurface the Bond No. o sults in a multip ed only after all in GR-CCL-C es). Pump 25	I bocations and in file with BLM le completion or requirements, in ML logs. Per solution of the solution of th	measured and true M/BIA. Required so measured and true M/BIA. Required so recompletion in including reclamate reforate (8/21/08 HCL (7/1/09).	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI OIL CONS DIST. n System negton 1998XM0132SE)	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has
13. Describe Proposed or If the proposal is to de Attach the Bond under following completion testing has been completed that the sign of the pressure test case Fruitland Coal from Frac w/52,700 ga	the foregoing is	true and correct. Electronic Submission # For DUGAN PRODUC True and to AFMSS for proc LEXANDER	give subsurface the Bond No. o sults in a multip ed only after all in GR-CCL-C es). Pump 25	blocations and in file with BLM le completion or requirements, in the legal state of the	weasured and true A/BIA. Required so recompletion in including reclamate erforate (8/21/08 HČL (7/1/09). Well Information to the Farmin on 07/02/2009 (6	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI OIL CONS DIST. n System negton 1998XM0132SE)	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has L 7 '09
13. Describe Proposed or If the proposal is to de Attach the Bond under following completion testing has been completed that the sign of the pressure test case Fruitland Coal from Frac w/52,700 ga	the foregoing is	true and correct. Electronic Submission # For DUGAN PRODUC True and to AFMSS for proc LEXANDER	give subsurface the Bond No. o sults in a multip ed only after all an GR-CCL-C es). Pump 25	blocations and in file with BLM le completion or requirements, in ML logs. Per solution of the	Well Information of to the Farming on 07/02/2009	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI OIL CONS DIST. n System agton 1995XM0132SE)	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has
13. Describe Proposed or If the proposal is to de Attach the Bond under following completion testing has been completed that the sign of the pressure test case Fruitland Coal from Frac w/52,700 ga	the foregoing is	cration (clearly state all pertinerally or recomplete horizontally, it will be performed or provide operations. If the operation repandonment Notices shall be fill nal inspection.) Digit for 30 mins, held. Rule w/4 spf (total 25', 100 hole 20/40 sand (7/1/09). True and correct. Electronic Submission # For DUGAN PRODUNTITIES FOR DUGAN PRODUCTION PROD	give subsurface the Bond No. o sults in a multip ed only after all an GR-CCL-C es). Pump 25	blocations and in file with BLM le completion or requirements, in the second se	Well Information of to the Farming on 07/02/2009	vertical depths of all pertir subsequent reports shall be a new interval, a Form 316 ion, have been completed, B) RCVD JUI OIL CONS DIST. n System negton 1998XM0132SE)	nent markers and zones. filed within 30 days i0-4 shall be filed once and the operator has