submitted in lieu of Form 3160-5

# RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JUN 28 2009

Bureau of Land Management

	Sundry Notices and Reports on V	Wells	ramington ridio Unit	700	
1.	Type of Well		-	5. 6.	Lease Number SF - 078002 If Indian, All. or
	GAS				Tribe Name
2.	Name of Operator			7.	Unit Agreement Name Huerfano Unit
	BURLINGTON RESOURCES OIL & GAS	COMPANY LP			J
3.	Address & Phone No. of Operator	· · · · · · · · · · · · · · · · · · ·	A STATE OF THE STA	- 8.	Well Name & Numbe Huerfano Unit 112
	PO Box 4289, Farmington, NM 87499	9 (505) 326-9700		9.	API Well No.
_				-	30-045-05866
•	Location of Well, Footage, Sec., T, R,		,	10.	Field and Pool
	Surf: Unit F (SENW), 1650' FNL & 1650' FWL, Section 17, T26N, R10W, NMPM			11.	Gallup/MesaVerde/Pe County and State San Juan, NM
2.	CHECK APPROPRIATE BOX TO IT		E OF NOTICE, REPORT, OT	THER I	DATA
2.	Type of Submission Type of Action X Notice of Intent	on Abandonment	Change of Plans	THER I	OATA Other - TA
2.	Type of Submission Type of Action X Notice of Intent	on Abandonment Recompletion	Change of Plans New Construction	THER I	
2.	Type of Submission Type of Action  X Notice of Intent  Subsequent Report	on Abandonment	Change of Plans	THER I	Other - TA
2.	Type of Submission Type of Action  X Notice of Intent  Subsequent Report	n Abandonment Recompletion Plugging	Change of Plans  New Construction  Non-Routine Fracturing	THER I	Other - TA RCVD JUN 29'09
	Type of Submission Type of Action  X Notice of Intent  Subsequent Report	Abandonment Recompletion Plugging Casing Repair Altering Casing	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off	THER I	Other - TA  RCVD JUN 29'09  OIL CONS. DIV.
3. Bur	Type of Submission X Notice of Intent Subsequent Report Final Abandonment  Describe Proposed or Completed Open Subsequent Resources wishes to Plugback the	Abandonment Recompletion Plugging Casing Repair Altering Casing erations e Gallup/MesaVerde	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection  /PC and put this well into TA st	<i>Y</i>	Other TA  RCVD JUN 29'09  OIL CONS. DIV.  DIST. 3
3. Bur	Type of Submission X Notice of Intent Subsequent Report Final Abandonment  Describe Proposed or Completed Ope	Abandonment Recompletion Plugging Casing Repair Altering Casing erations e Gallup/MesaVerde	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection	<i>Y</i>	Other TA  RCVD JUN 29'09  OIL CONS. DIV.  DIST. 3
3. Bur	Type of Submission X Notice of Intent Subsequent Report Final Abandonment  Describe Proposed or Completed Open Subsequent Resources wishes to Plugback the	Abandonment Recompletion Plugging Casing Repair Altering Casing erations e Gallup/MesaVerde	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection  /PC and put this well into TA st	<i>Y</i>	Other TA  RCVD JUN 29'09  OIL CONS. DIV.  DIST. 3
3. 3urvel:	Type of Submission  X Notice of Intent  Subsequent Report  Final Abandonment  Describe Proposed or Completed Open Unington Resources wishes to Plugback the bore schematics.  I hereby certify that the foregoing is the submission of the submission	Abandonment Recompletion Plugging Casing Repair Altering Casing Prations e Gallup/MesaVerde	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection  /PC and put this well into TA st	atus, po	Other TA  RCVD JUN 29'09 OIL CONS. DIV.  DIST. 3  er the attached procedure.
3. 3urvel:	Type of Submission  X Notice of Intent  Subsequent Report  Final Abandonment  Describe Proposed or Completed Open Unington Resources wishes to Plugback the bore schematics.  I hereby certify that the foregoing is the submission of the submission	Abandonment Recompletion Plugging Casing Repair Altering Casing Prations e Gallup/MesaVerde	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection  /PC and put this well into TA st	atus, po	Other TA  RCVD JUN 29'09  OIL CONS. DIV.  DIST. 3
3.  3ur  4.  6igr	Type of Submission  X Notice of Intent  Subsequent Report  Final Abandonment  Describe Proposed or Completed Open Unington Resources wishes to Plugback the bore schematics.  I hereby certify that the foregoing is the submission of the submission	Abandonment Recompletion Plugging Casing Repair Altering Casing erations e Gallup/MesaVerde TA - crue and correct.	Change of Plans  New Construction  Non-Routine Fracturing  Water Shut off  Conversion to Injection  /PC and put this well into TA st	atus, po	Other TA  RCVD JUN 29'09  OIL CONS. DIV.  DIST. 3

NMOCD 67/8



## ConocoPhillips Huerfano 112 (GP) Plugback

Lat 36° 29' 27.204" N Long 107° 55' 19.74" W

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

#### PLUGBACK PROCEDURE:

- 1. This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- 2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
- 4. Plug #1 (Gallup perforations and top: 5936' 5550'): RIH and set 4.5" cement retainer at 5600'. Load casing and circulate well clean. Pressure test tubing to 1000 PSI. Pressure test casing to 800#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 107 sxs Class B cement; squeeze 73 sxs outside 4.5" x 7" annulus (100% excess) to fill the Gallup perforations and leave 34 sxs inside 4.5" casing to cover the Gallup top. TOH.
- 5. Plug #2 (Mesaverde top, 3600' 3560'): Perforate 3 squeeze holes at 3600'. Attempt to establish rate into squeeze holes if the casing pressure tested. Set 4.5" cement retainer at 3550'. Establish rate into squeeze holes. Mix and pump 27 sxs Class B cement, squeeze 15 sxs outside the 4.5" x 7" casing annulus and leave 12 sxs inside casing to cover the Mesaverde top. TOH.
- 6. Plug #3 (Pictured Cliffs and Fruitland annulus: 2285' 1400'): RIH and set 4.5" cement retainer at 2235'. Mix 105 sxs Class B cement; squeeze 13 sxs outside 7" x 8.75" casing, 88 sxs outside 4.5" x 7" annulus and leave 4 sxs inside 4.5" casing below CR. PUH to 2000' and reverse circulate the well clean.
- 7. Pressure test the 4.5" casing to 500 PSI. If the casing does test, then notify the BLM to witness a Mechanical Integrity Test. Record a 30 minute pressure test at 500 PSI on a chart. Fill the casing Cortron R-2264 corrosion inhibitor from 2285' to surface. TOH and LD the tubing. ND the BOP and NU the wellhead. RD and MOL.

## Huerfano Unit #112

#### Current Gallegos Gallup / Basin Dakota

1650' FNL, 1650' FWL, Section 17, T-26-N, R-10-W, San Juan County, NM

Today's Date: 6/11/09

Lat: 36°29'27.204" N / Long: 107°55'19.704"W API #30-045-05866

Spud: 7/29/59 Completion: 8/18/59 Elevation: 6583' GL

6594' KB

15" hole

10.75", 32.75#, SW Casing set @ 332' Cement with 195 sxs, circulate to surface

(189 joints, 4.7#, J-55, SN and perf sub with

2.375" Tubing @ 5856'

rods and pump)

7" TOC @ 1440' (1959 TS)

DV Tool @ 2235' Cemented with 110 sxs TOC at 1440' (1959 TS)

7" TOC @ 4730' (1959 TS)

Gallup Perforations:

5650' - 5910'

Holes in casing 3843' - 4029', sqz'd with 177 cf, Top of sqz calc, 3144' (1981)

Ojo Alamo @ 1064'

Fruitland @ 1701'

Pictured Cliffs @ 2045'

Mesaverde @ 3550'

Gallup @ 5637'

Dakota @ 6564'

Dakota Perforations:

6570' -- 6714' Squeeze off perforations with 150 sxs cement (1980)

4.5",10.5#, K-55 casing set @ 5936' liner un-cemented to surface

TD 6794' **PBTD 5936'** 

8.75" Hole

7", 23#, SW casing set @ 6794' Cemented with 250 sxs, TOC at 4730' (1959 TS)

Kirtland @ 1178'

### Huerfano Unit #112 Proposed Plugback


Today's Date: 6/11/09 Snud 7/29/59 Completion 8/18/59 Elevation 6583' GL 10 75", 32 75#, SW Casing set @ 332' Cement with 195 sxs, circulate to surface 6594' KB 15" hole 7" TOC @ 1440' (1959 TS) Ojo Alamo @ 1064' Set CR @ 2235' Kırtland @ 1178' Tool @ 2235'
Cemented with 110 sxs
TOC at 1440' (1959 TS)
Plug #3: 2285' - 1400'
Class B cement, 105 sxs
'2 outside 7" x 8 75", DV Tool @ 2235' Fruitland @ 1701' 13 outside 7" x 8 75", 88 outside 4.5" x 7" 4 in 4.5" below CR Perforate @ 2285' Pictured Cliffs @ 2045' Holes in casing 3843' – 4029', sqz'd with 177 cf, Top of sqz calc, 3144' (1981) Plug #2: 3600' - 3500' Class B cement, 27 sxs 12 inside 4 5" casing, 15 outside 4 5" x 7" Cement Retainer @ 3550' annulus Perforate 4.5" casing @ 3600' Mesaverde @ 3550' 7" TOC @ 4730' (1959 TS) Plug #1: 5936' - 5550' Class B cement, 107 sxs. Set CR @ 5600' Gallup @ 5637' Gallup Perforations. 5650' - 5910' 4.5",10.5#, K-55 casing set @ 5936' liner un-cemented to surface Dakota @ 6564' Dakota Perforations 6570' ~ 6714' Squeeze off perforations with 150 sxs cement (1980) 8 75" Hole TD 6794'

> 7", 23#, SW casing set @ 6794' Cemented with 250 sxs, TOC at 4730' (1959 TS)

#### Current Schematic

## ConocoPhillips

Well Name: "HUERFANO UNIT #112



Page 1/1

Report Printed: 6/16/2009