Form 3160-5 (August 2007)

Approved By STEPHEN MASON

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

LINITED STATES

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM AP	PKOVED
OMB NO. 1	1004-0135
Expires: July	y 31, 2010

Date 06/26/2009

	Expire	es: July 3	Ι,
Lease Sc	rial No.		

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an		NMSF080238A			
abandoned well. Use form 3160-3 (APD) for such proposals.			6. If Indian, Allottee of	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well			8. Well Name and No CHACO LTD 3J	•	
Oil Well Gas Well Ot		5			
Name of Operator Contact: PAUL THOMPSON THOMPSON ENGINEERING & PRODES Mail: paul@walsheng.net				9. API Well No. 30-045-24611-00-S1	
3a. Address 7415 E MAIN ST FARMINGTON, NM 87402		3b. Phone No. (include area code) Ph: 505-327-4892 Fx: 505-327-9834	10 Field and Pool, or WAW	10 Field and Pool, or Exploratory WAW	
4. Location of Well (Footage, Sec., 1	T, R., M., or Survey Description)	11. County or Parish,	and State	
Sec 12 T26N R13W SWNW 1 36.50485 N Lat, 108.17621 W			SAN JUAN CO	UNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE OF N	OTICE, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Nisting of Intent	☐ Acidize	☐ Deepen	Production (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	Alter Casing	Fracture Treat	Reclamation	☐ Well Integrity	
Subsequent Report	Casing Repair	☐ New Construction	Recomplete	Other	
Final Abandonment Notice	Change Plans	▶ Plug and Abandon	Temporarily Abandon	_	
•	Convert to Injection	Plug Back	☐ Water Disposal		
Attach the Bond under which the we following completion of the involved	ally or recomplete horizontally, or will be performed or provided operations. If the operation rebandonment Notices shall be fil final inspection.)	give subsurface locations and measure the Bond No. on file with BLM/BL/sults in a multiple completion or recoled only after all requirements, included	red and true vertical depths of all pertical Required subsequent reports shall be ompletion in a new interval, a Form 31 ling reclamation, have been completed	inent markers and zones. e filed within 30 days 60-4 shall be filed once	
			RCVD JU DIL CON		
			S		
14. I hereby certify that the foregoing i	Electronic Submission # For THOMPSON ENG	F71220 verified by the BLM Wel BINEERING & PROD CO, sent to sessing by STEVE MASON on 0	the Farmington		
	OMPSON	Title ENGIN	• • •		
Signature (Electronic	Submission)	Date 06/22/2	009		
	THIS SDACE E	OR FEDERAL OR STATE	OFFICE LISE		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

TitlePETROLEUM ENGINEER

Office Farmington

Walsh Engineering and Production

P & A Procedure for Thompson Engineering and Production Corp. Chaco Ltd. #3J

Location: NW/4 Sec 12 T26N R13W Date: October 6, 2008

San Juan County, NM

Field: WAW Pictured Cliffs Elev: GL 6039'
Surface: Navajo 2-7/8" @ 1325'

Minerals: BLM NMSF 080238A PBTD 1227' GL (CIBP)

Procedure:

1. MOL and RU completion rig. Hold safety meeting.

- 2. NU 2-3/8" relief line. Blow well down and kill with water if necessary.
- 3. Lay down the polished rod, two 6' and two 2' 5/8" pony rods, 45 plain 5/8" rods, two 1-1/4" sinker bars, and the pump plunger. TOH and lay down 36 joints of 1-1/2" IJ tubing and the pump barrel.
- 4. Remove 2-7/8" tubing head.
- Casing Ca
- 7. Cut off wellhead and install dryhole marker. Reclaim location as per BLM specifications.

Paul C. Thompson, P.E.