UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

6 If Indian, Allottee or Tribe Name

5. Lease Serial No.

_		_	

Do not use this form for proposals to drill or to re-enter and 29 2009 abandoned well. Use Form 3160-3 (APD) for such proposals.

Liureau of Land Mann SUBMIT IN TRIPLICATE - Other instructions on page 2 mington Field Office If Unit or CA/Agreement, Name and/or No. 1 Type of Well 8. Well Name and No. Oil Well X Gas Well Other #13 Carracas 18 B 2. Name of Operator Energen Resources Corporation 9. API Well No. 3a Address 3b. Phone No. (include area code) 30-039-24282 2010 Afton Place, Farmington, NM 87401 (505) 325-6800 10 Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Basin Fruitland Coal At Surface: 790' FSL, 900' FWL Sec. 18, T32N, R4W 11. County or Parish, State Rio <u>Arriba</u> 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Alter Casing Fracture Treat Reclamation Well Integrity Subsequent Report New Construction Casing Repair Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.) Energen Resources Plans to Plug and Abandon the Carracas 18B #13 as follows: 1. MIRU. ND Wellhead. NU BOP. 2. TOH w/ 2-3/8" tbg, 1/4" capillary tbg, and ESP. 3. TIH w/ 5-1/2" CIBP and set @ 4100'. Pump a cement plug across the Fruitland top inside casing f/ 4000' to 4100' w/ 18 sks of neat cement (50% Excess). Pull the above cement. Wait 4 hrs and tag cement. TOH w/ tba. 34201 4. TIH w/5-1/2" CIBP and set @ 3850'. Pump a cement plug inside casing f/3560' to 3850' w/84 sks of neat cement (50% Excess) to cover the Kirtland and Ojo Alamo tops. Pull tbg above cement. Wait 4 hrs and tag coment. Nacimon ro ply 2310 -2216 5. Pull tbg up to 380'. Set a balanced cement plug inside casing f/380' to surface w/66 sks of neat cement (50% Excess). Pull the out of casing and top off w/ cement. 6. ND BOP and cut off casing below surface casing flange. Install P&A marker w/ cement to comply w/ regulations. RDMO, cut off anchors and restore location. RCVD AUG 3'09 *See attached wellbore diagrams. OIL CONS. DIV. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Title Kirt. District Engineer Signature Date 7/30/2009 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title Approved by Original Signed: Stephen Mason JUL 3 1 2009 Conditions of approval, if any, are attached Approval of this notice does not want although the applicant holds legal or equitable title to those rights in the subject lease which we also applicant holds legal or equitable title to those rights in the subject lease which we are Office entitle the applicant to conduct operations thereon

Form	TA-0000-0005	



AN ENERGEN COMPANY

En	aine	erina	Chart
	91110	oi iiig	Onari

Subject LATTA (AS 18B #13 Wellbore Diagram

Sheet No. File

Appn. $\frac{7/29/209}{}$

124 Surface Hole
95/8", 36 ppf, J-55 set @ 360 ft 51/2", 17 and 15.5 ppf, J-55 set @ 4267 ft Window f/ 3887 ft to 3897 ft
Open Hole Sidetrack f/3877 fe to 5367 fe FRC Perts 434" Hole PBTD 4221 fe TD 4270 fe

834" Hole

	•
Form	TA-0000-0005

83/4" Hole



Engineering	Chart
. `	

Subject LATTA (AS 18B #13 Proposed P\$A

Sheet No. Date 7/29/2009

1214 Surface Hole 95/8", 36 ppf, J-55 set@ 360 PE Plug #3: Wesks, 380 fe to surface 5/3", 17 and 15.5 ppf, J-55 st @ 4267ft Window f/ 3887 ft to 3897 (t open Hole Sidetrack f/3877 ft to 5367 ft Pluy#1 4000to 4/00 434" Hole FRC Perfs 4140 fe to 4163 ft CIBP & flooft EPBTD 4/22/ fe TD: 4270 FE

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: 13 Carracas 18B

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Bring the top of the Fruitland/Kirtland/Ojo Alamo plug to 3420'.
- b) Place the Nacimiento plug from 2316' 2216'.
- c) Place the Surface plug from 410' to surface.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.