SUNDRY I  Do not use this abandoned well	s form for proposals to I. Use form 3160-3 (API	VITERIOR GEMENT RECE RTS ON WELLS  drill or to re-enter an O) for such proposition	OMB Expires  CREPORT  S. Lease Serial No. 142060462  6. KIndian, Allotte UTE-MOUNT	ee or Tribe Name
SUBMIT IN TRI	PLICATE - Other instruc	tions on revers BEIM DUR	ANGO	greenent, waite and/or wo.
Type of Well     Oil Well	er		8. Well Name and 1 UTE DOME 20	No.
2. Name of Operator XTO ENERGY	Contact:	HOLLY PERKINS E-Mail: Regulatory@xtoenergy.co	9. API Well No. 30-045-2460	5-00-S1
3a. Address 2700 FARMINGTON AVE, BLDG K, SUITE 1 FARMINGTON, NM 87401		3b. Phone No. (include area code) Ph: 505.324.1090 Ext: 4020 Fx: 505.564.6700	10. Field and Pool UTE DOME	, or Exploratory
4. Location of Well (Footage, Sec., 7 Sec 2 T31N R14W NWSE 158	-	1)	11. County or Pari SAN JUAN C	sh, and State
12. CHECK APPE	ROPRIATE BOX(ES) TO	D INDICATE NATURE OF N	OTICE, REPORT, OR OTH	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent  Subsequent Report  Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	Water Shut-Off Well Integrity Other
following completion of the involved testing has been completed. Final Al determined that the site is ready for f	eration (clearly state all pertine ally or recomplete horizontally, rk will be performed or provide operations. If the operation rebandonment Notices shall be fixed in the performed or performed or performed or performed by the performed or performed by the performed of the performed of the performed or	nt details, including estimated startin give subsurface locations and measu the Bond No. on file with BLM/BLA sults in a multiple completion or reco led only after all requirements, includ-	g date of any proposed work and ar red and true vertical depths of all p . Required subsequent reports sha impletion in a new interval, a Form	ertinent markers and zones. Il be filed within 30 days 3160-4 shall be filed once
XTO Energy Inc. has plugged  1) MIRU serv rig & cmt equip 2) TIH & set cmt ret @ 2513' 3) PT tbg to 1000 psig; held 4) Mixed & ppd 12 sx cmt (15 5) Mixed & ppd 12 sx cmt (15 6) Mixed & ppd 37 sx cmt (15 7) Cut off WH. Installed dry 1 8) RDMO serv rig. 9) Marie Gray-Lope w/Colora	OK. PT csg to 500 psig; 5.6 ppg) fr/2513' - 2355'. 5.6 ppg) fr/1256' - 1098'. 5.6 ppg) fr/368' - surf. Go hole marker w/15 sx cmt.	lorado BLM on loc. held OK.	SEE ATTACHED CONDITIONS OF APPERC	0E0 3000

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #24672 verified by the BLM Well Information System

For XTO ENERGY, sent to the Durango

Committed to AFMSS for processing by RUTH RICHARDSON on 11/03/2003 (04RR0979SE). **REGULATORY SUPERVISOR** 

Name (Printed/Typed) DARRIN STEED Signature (Electronic Submission) Date 11/03/2003

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Title

Approved By

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

XTO Energy

Tribal Lease: 14-20-604-62

Ute Mountain Ute: Ute Dome #20-A

Sec. 2, T. 31 N., R. 14 W. San Juan County, New Mexico

## **Conditions of Approval - Subsequent Report of Abandonment**

- 1. Approval of this Notice is for the completed down-hole plugging of the well. Surface reclamation must be completed in accordance with Ute Mountain Ute Tribal/BIA requirements. Please contact Gordon Hammond of the Ute Mountain Ute Energy Office for specific reclamation requirements and seed mixtures.
- 2. When the wellsite is ready for final surface inspection, please contact this office and the Ute Mountain Ute Energy Office in order that an onsite inspection can be made. Final Abandonment Notice (FAN) can be submitted via Sundry Notice at that time.
- 3. After the FAN is approved by this office, your liability associated with the subject well will terminate.