submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

グ温D・	5.	Lease Number
2009	6.	SF-078171 If Indian, All. or Tribe Name
	7.	Unit Agreement Name
A-11-11-11-11-11-11-11-11-11-11-11-11-11	 8.	Well Name & Number Aztec Federal 1
	9.	API Well No.
		30-045-09319
	10.	Field and Pool
MPM	Basi 11.	n Dakota County and State San Juan Co., NM
E, REPORT, O	OTHER I	DATA
ge of Plans		Other –
Construction Routine Fracturing	g	RCVD OCT 15 '09
Shut off ersion to Injection	1	OIL CONS. DIV. DIST. 3
		7.7.1. 1
hematic. ENTIAL EXIST		<u>Sechnician</u> Date 10.
		OCT 0 7 2003

NMOCD

ConocoPhillips Aztec Federal #1 (MV DK) Plug and Abandon

Lat 36° 47′ 38.39″ N Long 107° 56′ 24″ W

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- This project requires the Operator to obtain an approved NMOCD C-144 CLEZ Closed-Loop System Permit for the use of an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
- 2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.

3.	Rods: Yes, No _X_, Unknown;
	Tubing: Yes, No X, Unknown, Size, Length;
	Packer: Yes, No _X, Unknown, Type
	If this well has rods or a packer, then modify the work sequence in step #2 as
	appropriate. Round trip a 4.5" casing scraper to 4147' or as deep as possible

4. Plug #1 (Chacra perforations and top: 3512' – 3412'): Perforate 3 squeeze holes at 3512'. Set 4.5" cement retainer at 3462'. Circulate well clean. Mix and pump 80 sxs Class B cement, squeeze 60 sxs below the cement retainer (Extra due to casing leaks) and leave 20 sxs inside casing. TOH with tubing.

5. Plug #2 (Pictured Cliffs and Fruitland Coal tops: 2780' – 2573'): Mix 26' sxs cement and spot a balanced plug inside casing to cover the Pictured Cliffs and Fruitland tops. PUH with tubing.

1428 1193

- 6. Plug #3 (Kirtland and Ojo Alamo tops: 1446' 1232'): Mix 20 sxs cement and spot a balanced plug inside casing to cover these tops. PUH.
- 7. Plug #4 (Surface Casing shoe, 357' to Surface): Connect the pump line to the bradenhead valve and attempt to pressure test the BH annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 25 sxs Class B cement and spot a balanced plug inside the casing from 307' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the 4.5" casing from 307' and the BH annulus to surface. Shut well in and WOC.

8. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

Current Schematic

ConocoPhillips Well Name: AZTEC FEDERAL #1

4PI/UWI 3004509:		Surface Legal Location Unit J-24-30N-11VV	Field Name BSN DK(PRO	GAS) #0068	State/Proutse (Mell County tratto) Type NEVY MEXICO	Ec
ored Ekle 6,1	170:00	Original KB/RT Eleuation (16) 6,182.00	KB-G	round Distance (ft) 12.00		
715/4	47537259		Well Config	Øriginal	Hole, 9/14/2009 9:54:39 AM	Ta
ftkb (MD)			Sc	nematic - Actu	ual Frm Final	
0					Surface Casing Cement, 12-307, 8/16/1964,	
12		111671715555551165755	4111414177	<u> </u>	/ 175 sx cement. Cemented circulated. }/^//SUMace, 8/5/8//,/8/097/H,/12/HKB/,307/HKB/	
306					// Cement Squeeze, 12-588, 8/19/1995,	
307					Squeezed hole @ 588' w/ cement.	
312				—	Cément Squeeze, 230-625, 8/22/1995, 30 sx CI G cmt. from 230'-625' w/ 75% eff.	
2,623			Ø		Cement Squeeze, 1,043-1,089, 8/23/1995, PICTURED CLIFFS, 2,6	623
2,730					Holes from 1043'-1089'. Spot 20 sx Cl G cmt. LEWIS, 2,730 — LEWIS, 2,730 —	
2,744					Production Casing Cement, 12-2,745,	
2,747	* *	a, n y se			9/1/1964, 3rd stage: 525 sx 50/50 poz cmt. + 100 sx 50/50 poz cmt. TOC @ surface (CBL	
3,295	Hvdraulic	Fracture, 9/25/2001,	XX		8/95)	
3,462	200,000# 20	/40 Brady sand; 663 _		XX.	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	
4,004	bbis 3	0# LG w/ 75Q foam; 1,146,500 scf N2.	N XX	122	150 sx GIB cmt. BOC @ 3304 & TOC @ 3050 (CBL 9/01)	
- 4,147		111 10,000 001 112.	888	889	Chacra, 3,462-4,004, 9/25/2001	_
4,295			- W		Cement Plug, 3,422-3,989, 8/25/2009, RE CLIFFHOUSE, 4,295	
4,480					Cement Squeeze, 3,429-3,989, 8/25/2009 MENEFEE, 4,480	
4,623					\$300 PSI SQUEEZE, 3,462-4,004, 2/27/2008 	
4,628	Hydraulic	Fracture, 9/25/2001,			Cement Squeeze, 3,462-4,005, 2/14/2008	
4,676 4,876		0 Brady sand; 1,158 —	-1 4			
4,912	-	bblš SW.			Hole @ 4456' squeezed w/ 75 sx Cl G.cmt.	
4,935					TOC@ 4165' w/ 75% eff. Bridge Plug - Temporary, 4,623-4,628 POINT LOOKOUT, 4,9	335
5,054				-88	Menetee, 4,676-4,876, 9/24/2001	
5,057	Hydraulic 85.000#120/4	Fracture, 9/25/2001, 0 Brády šand; 1,975 —			Production Casing Cement, 4,278-5,055, 9/1 / 1964, 2nd stage: 200 sx 50/50 poz cmt.	
5,150		bbls SW.			TOC @ 4278' w/ 75 eff. MANCOS, 5,150 -	
5,248		1.6	1 💥		Point Lookout, 4,912-5,248, 9/22/2001 Cement Squeeze, 4,803-6,105, 8/22/1995,	
6,180	Hydrautic F	racture, 10/28/1964,			T-100 sx CFG cmf. from 4803-6105 W/75% GALLUP, 6,180 -	
6,915	10,000#	40/60 sand; 10,000# 🔨			Cement Squeeze, 5,055-6,107, 2/14/1979, GREENHORN, 6,915	5
7,033		nd; 24,300 gals SW. \ 3, New PBTD due to		7.4	Holes from 5055'-6107'. Squeezed w/ 500	
7,041	fish. In 2	001 milled on fish to			sx CI C cmt. Dakota, 7,033-7,041, 10/14/1964	
7,073		then decided to quit prior downhole fire				
7,076 7,105	_	ish in hole originally.			Dakota, 7,112-7,128, 10/14/1964 Fish, 7,076-7,253, Casing collapsed @ 7082',DAKOTA A, 7,105	
7,112	Hydraulic F	racture, 10/28/1964,		1/1	/ pinched tog. @ 7082', chemical cut tog. @	
7,112	Frac'd w/	42,000# 20/40 sand; —	-1 ///		// 7076'. Left in hole-sawtooth collar, exp. / check, seat joint, SN, 6jts tbg, & cut off joint	
7,165	49,	700 ĝals slickwater.			f of 5.86', 8/31/95	;
7,234		racture, 10/28/1964,		14.	Dakota, 7,234-7,252, 10/14/1964 Production Casing Cement, 6,685-7,268,	
7,252		40/60 sand; 14,000# — nd; 28,100 gals SW.	一级》	2 1/2+	9/1/1964, 1st stage: 150 sx 50/50 poz cmt	
7,253	20/40 3G	20,100 gais 311.			followed by 100 sx reg. cmt. TOC @ 6685' w/75% eff.	
7,267					∫ _F Cement Plug, 7,253-7,268, 9/1 /1 964	
7,268		TD, 7,268, 9/1/1964			Production, 4 1/2in, 4.000in, 12 ftKB, 7,268 ftKB	

Page 1/1

Report Printed: 9/14/2009

Proposed Wellbore

ConocoPhillips Well Name: AZTEC FEDERAL #1

API / UWI 30045093	19	Surface Legal Location Unit J-24-30N-11VV	Field Name BSN DK(PR			NEW MEXICO		onfiguration Type	[Edi
Fround Elev	ration (ft) 170.00	Original KB/RT Elevation (ft) 6:182.00		-Ground Dis		. KB-Casing Flange Distance (ff) KB	Tubing Hanger Distance	(ft)
and the second	ar energy are as Likelia (N.C.)	erst-der Steinbet "Pro-Pauliere, vanganne vilkeut algebrakeise troopie	Vell:Confi	α ≟ Ori	AND THE PARTY OF	le, 9/22/2009 10:08:42 AM		The state of the s	
fikB.				O DELESTION AND					
(MD)			Application Section	Schematic	- Actual			Frm Final	
0									
12	212122221122					ACCOUNT OF THE PARTY OF THE PAR		-	
306						Surface Casing Cement, 12-307, 8 175 sx cement. Cemented circula			
307		₽ a ±4 € . * *				- Surface, 8 5/8in, 8 097in, 12 ftKB,			
312		;				Cement Plug, 12-357 Cement Plug, 1,232-1,446			
1,282		t .				Production Casing Cement, 12-2,7		OJO ALAMO, 1	1 ,282
2,623				TOTAL S		9/1/1964, 3rd stage: 525 sx 50/50 f 100 sx 50/50 poz cmt TOC @ st		PICTURED CLI	IFFS,
2,730					3	/ 8/95)		2,623 LEWIS, 2,73	30
2,744		,				Cement Plug, 2,573-2,780 Squeeze Holes, 3,295, 9/21/2001			
2,747		•				/ Cement Plug, 3,412-3,512	•		
3,295		1	44		_]•/;	Chacra, 3,462-4,004, 9/25/2001 Cement Plug, 3,422-3,989, 8/25/20	009,	1	
3,462		ulic Fracture, 9/25/2001, ‡20/40 Brady sand, 663	B - XXX	<i></i>		Re-squeeze Chacra perfs. Did not squeeze.	get a good		
4,004		Is 30# LG w/ 75Q foam;	1 8	- 2		Squeeze. Cement Squeeze, 3,429-3,989, 8/.	25/2009	1	•
4,147		1,146,500 scf N2.	\		1.				
4,295			777	7	<u>a</u>	Fill/Cement(Cmt/sand/shale return		CLIFFHOUSE,	4,295 —
4,480		,				4,147-4,623, Could not completely plug after squeezing Chacra.	drill out cmt	 MENEFEE, 4,	,480
4,623						Bridge Plug - Temporary, 4,623-4,		1	
4,628		0				bridge plug to isolate the Chacra fi below.	rom the MV		
4,676		ulic Fracture, 9/25/2001,		- 2					
4,876	50,000#2	1,158 Brady sand, 1,158 المارك 				Menefee, 4,676-4,876, 9/24/2001			
4,912		}		- 2	4.				
4,935	,				4 —	Production Casing Cement, 4,278-	5 055	POINT LOOKOUT	Г, 4,935 —
5,054						~9/1/1964, 2nd stage: 200 sx 50/50			
5,057	Hydrau 85.000#2	ılic Fracture, 9/25/2001, !0/40 Brady sand; 1,975 —		-88	8	TOC @ 4278' w/ 75 eff. Point Lookout, 4,912-5,248, 9/22/2	2001		
5,150		bbis SW.	- 💥	- 88	X -1			MANCOS, 5,	150
5,248		4		× × × × × × × × × × × × × × × × × × ×		Cement Squeeze, 5,055-6,107, 2/	14/1979.		
6,180				882	\$4	- Holes from 5055'-6107' Squeezec		GALLUP, 6,1	180
6,915		ic Fracture, 10/28/1964, 0# 40/60 sand; 10,000# \				CI C cmt.		GREENHORN,	6,915
7,033	20/40	sand; 24,300 gals SW.			4.1	Dakota, 7,033-7,041, 10/14/1964			
7,041		,073, New PBTD due to 1 milled on fish to 7073				Dakota, 7,033-7,047, 1071471904]			
7,073	but the	n decided to quit milling							
7,076	aue to pri	or downhole fire that left fish in hole originally.				(B)			
7,105				Oa P		Dakota, 7,112-7,128, 10/14/1964 Fish, 7,076-7,253, Casing collapse	d @ 7082'	DAKOTA A, 7	,105
7,112		c Fracture, 10/28/1964, w/ 42,000# 20/40 sand;				pinched tbg. @ 7082', chemical cu	ıttbg.⊘2		
7,128		49,700 gals slickwater.		WIE		7076'. Left in hole-sawtooth collar seat joint, SN, 6jts tbg, & cut off jo			
7,165						8/31/95		DAKOTA B, 7,	,165
7,234		ic Fracture, 10/28/1964, 0# 40/60 sand; 14,000#		1-8	11/	Dakota, 7,234-7,252, 10/14/1964 Production Casing Cement, 6,685-	7,268.		
7,252		u# 40/60 sand; 14,000# sand, 28,100 gals SW.				9/1/1964, 1st stage: 150 sx 50/50	poz cmt		
7,253		1				followed by 100 sx regiomt TOC 75% eff.	@ 6685' w/		
7,267						Cement Plug, 7,253-7,268, 9/1/196			
7,268		TD, 7,268, 9/1/1964			a 1	_ Production, 4 1/2in, 4.000in, 12 ftk _ftKB	(B, 7,268		
						W.O			

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

1235 LA PLATA HIGHWAY FARMINGTON, NEW MEXICO 87401

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: 1 Aztec Federal

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.
- 3. The following modifications to your plugging program are to be made:
- a) Place the Pictured Cliffs/Fruitland plug from 2672' 2278'.
- b) Place the Kirtland/Ojo Alamo plug from 1428' 1193'.

Note: H2S has been reported in the area of this well. It is imperative that H2S monitoring equipment and personnel be on location during plugging operations.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.