

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for ~~well proposals~~.)

1. oil well ☐ gas well ☐ other **DRY HOLE**
2. NAME OF OPERATOR  
**Bus Rx, Inc**
3. ADDRESS OF OPERATOR  
**P.O. Box 50325, Tucson, AZ 85703**
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: **2100 ESL, 230' F W L**  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

- ☐  
☐  
☐  
☐  
☐  
☐  
☐  
☒

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

DEC 09 1983

BUREAU OF LAND MANAGEMENT  
FARMINGTON RESOURCE AREA

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Plugged and abandoned as follows:

cement plug 2960 - 3050'

> 9.2 lb/A+ mud 2000 - 2960'

cement plug 1900 - 2000'

Heavy mud (> 9.2) 250' - 1900'

~~Heavy~~ cement plug 250 - 350' \* CASING BROKE AT 250'

Heavy mud 150 - 250'

cement plug 0 - 150'

ERECTED DRY HOLE MARKER, DISCED + SEEDING SITE TO  
FOREST SERVICE SPECS

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED C. A. Dally TITLE \_\_\_\_\_ DATE \_\_\_\_\_

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

24/100

1WR 2-14-85 BC

FARMINGTON COPY

APPROVED  
AS AMENDED

FEB 06 1985

M. MILLENBACH  
AREA MANAGER