

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API # 30-045-27590

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Larry Schlotterback
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name Florance P 003	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No
---------------------------------	---------------	----------

LOCATION OF RELEASE

Unit Letter G	Section 35	Township 30N	Range 8W	Feet from the	LATITUDE 36.77046	Feet from the	LONGITUDE 107.64113	County San Juan
-------------------------	----------------------	------------------------	--------------------	---------------	-----------------------------	---------------	-------------------------------	---------------------------

NATURE OF RELEASE

Type of Release: PRODUCED WATER (Coal)	Volume of Release – 6 Barrels	Volume Recovered – 4 Barrels
Source of Release: Production Water Tank	Date and Hour of Occurrence: 3/21/2009	Date and Hour of Discovery 1/5/2009 – 2:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD & BLM	
By Whom? Larry Schlotterback	Date and Hour: March 21, 2009 – 14:30	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD MAR 31 '09
OIL CONSV. DIV.
DIST. 3



If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

On Saturday, March 20, 2009, operations tech reported to the Coal Team Leader a spill on the Florance P 003. Approximately 6 bbls of produced water spilled from the production tank due to a hole in the fire tube. All fluid was contained by secondary containment; no fluid left location or breached the containment walls. When the report was made, a vacuum truck was in route to location to remove the remaining fluids in the tank and pickup any standing fluids. The vessel was locked out and production fluid was routed down the pipeline. The cause of the leak will be further investigated by RCFA.

Describe Area Affected and Cleanup Action Taken.* Soil on location and a nearby natural drainage was impacted. The area will be allowed to dry and any salt stain will be removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Larry Schlotterback		Approved by District Supervisor:  For: Charlie Perri	
Title: Field Environmental Coordinator		Approval Date: 8-19-09	Expiration Date:
E-mail Address: schlln@bp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/26/09	Phone: 505-326-9425		

* Attach Additional Sheets If Necessary

~ BP0923150157