Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

DEC 3 0 2009

RECEIVED

FORM APPROVED OMB NO. 1004-0137 Expires July 31, 2010

5. Lease Serial No.

NM-25857

SUNDRY NOTICES AND REPORTS ON WELLESU of Land Management

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		6 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well Oil Well X Gas Well Other 2. Name of Operator XTO ENERGY INC.		8. Well Name and No. WF FEDERAL 21 #1Y 9. API Well No.
3a. Address	3b. Phone No. (include area c	
382 CR 3100 AZTEC, NM 87410	505-333-3100	10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T, R, M, or Survey Description)		BASIN FRUITALND COAL
885' FSL & 856' FWL SWSW SEC.21(M)-T30N-	R14W N.M.P.M.	HAPER HILL FRUITLAND SAND PC
		11. County or Parish, State
		SAN JUAN NM
12. CHECK APPROPRIATE BOX(ES)	TO INDICATE NATURE OF NOT	rice, report, or other data
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent Acidiz	Decpen [Production (Start/Resume) Water Shut-Off
X Subsequent Report	Casing Fracture Treat Repair New Construction	Reclamation Well Integrity
		Recomplete Other
Final Abandonment Notice Change Plans Plug and Abandon X Temporarily Abandon		
Conve	t to Injection Plug Back	Water Disposal
13. Describe Proposed or Completed Operation (clearly state all per If the proposal is to deepen directionally or recomplete horizont. Attach the Bond under which the work will be performed or pr following completion of the involved operations. If the operatic testing has been completed. Final Abandonment Notices shall determined that the final site is ready for final inspection.) XTO Energy Inc., temporarily abandoned the copy of the chart with MIT results.	lly, give subsurface locations and measure ovide the Bond No. on file with BLM/BL/ n results in a multiple completion or record effect only after all requirements, including the control of the control	and true vertical depths of all pertinent markers and zones. A. Required subsequent reports shall be filed within 30 days impletion in a new interval, a Form 3160-4 shall be filed once ing reclamation, have been completed, and the operator has cort. Please also see the attached RCUD JAN 5'10
		OIL CONS. DIV.
		DIST. 3
Nuocd T/A EXPIRES 12-80-2014 MAY DIFFER. CONTACT BLM F FOR FEDERAL EXPIRATION.	BLM T/A EXPIRATION FIELD OFFI	JAN 0 4 2000 I
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)		
TEENA M. WHITING	Title REGULATO	RY COMPLIANCE TECHNICIAN
Signature 1 00 00 m (1) (4 10 0	Date 12/31/2009)

14. I hereby certify that the foregoing is true and correct Name (PrintedTyped)		
TEENA M. WHITING	Title REGULATORY COM	MPLIANCE TECHNICIAN
Signature Jelma M. Whiting	Date 12/31/2009	
THIS SPACE FOR	FEDERAL OR STATE OFFICE USE	
Approved by	Tule	Date
Conditions of approval, if any, are attached. Approval of this notice does not warrant the applicant holds legal or equitable title to those rights in the subject lease which wo entitle the applicant to conduct operations thereon		

Title 18 U S C Section 1001, and Title 43 U S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WF Federal 21 # 1Y (TA subsequent report) API#: 30-045-30031 T30N, R14W, Sec 21

12/30/09 - SITP 0 psig. SICP 10 psig. BD well. MIRU PU. TOH & LD rods & pmp. ND WH. NU BOP. TOH w/tbg & BHA. Contacted Kelly Roberts w/NMOCD & BLM @ 4:00 p.m. 12/30/09 & advised that TA procedures were commencing. TIH w/4-1/2" RBP & tbg. Set RBP @ 1,015'. Ld & PT 4-1/2" csg to 550 psig w/5 BLW for 30" w/psig chart. Tstd OK. Rls RBP. TOH & LD tbg & RBP. ND BOP. NU WH. SWI. SDFN.

12/31/09 – SICP 0 psig. RDMO PU.

