

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTFORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.5. Lease Serial No.
NMSF078155

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on reverse side.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other: UNKNOWN OTH8. Well Name and No.
WEST BISTI SWD 1

2. Name of Operator

Contact: JOHN C ALEXANDER
DUGAN PRODUCTION CORPORATION
Email: johncalexander@duganproduction.com9. API Well No.
30-045-33828-00-S1

3a. Address

FARMINGTON, NM 87499

3b. Phone No. (include area code)
Ph: 505-325-182110. Field and Pool, or Exploratory
SWD ENTRADA

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 35 T26N R13W SWNE 2500FNL 1855FEL

11. County or Parish, and State

SAN JUAN COUNTY, NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☒ Notice of Intent☐ Subsequent Report☐ Final Abandonment Notice☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Request permission to temporarily abandon the West Bisti SWD 1 wellbore. The well is shut-in waiting on approval from Navajo EPA to begin injection. NMOCD will be notified to conduct a casing pressure test.

TA approved until 2/1/11

RCVD JAN 14'10

Must comply with NMOCD Rules

19.15.25.12, 19.15.25.13 and

19.15.25.14

Notify NMOCD 24 hrs
prior to beginning
operations

OIL CONS. DIV.

DIST. 3

14. I hereby certify that the foregoing is true and correct.

Electronic Submission #79915 verified by the BLM Well Information System
For DUGAN PRODUCTION CORPORATION, sent to the Farmington
Committed to AFMSS for processing by STEVE MASON on 01/13/2010 (10SXM0061SE)

Name (Printed/Typed) JOHN C ALEXANDER

Title VICE-PRESIDENT

Signature (Electronic Submission)

Date 01/12/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By STEPHEN MASON

Title PETROLEUM ENGINEER

Date 01/13/2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

NMOCD