submitted in lieu of Form 3160-5	of Form 3160-5	of	lieu	in	submitted
----------------------------------	----------------	----	------	----	-----------

## UNITED STATES

## DEPARTMENT OF THE INTERIOR

	BUREAU (	OF LAND MANAGEMEN	r	
	Sundry Not	ices and Reports	on Wells	
1. Type of Well GAS			03 AUG -7 AII 13	5. Lease Number Jic Contract 150 600 If Indian, All. or Tribe Name Jicarilla Apache 7. Unit Agreement Name
2. Name of Operate BURLINGT			C 15 10 20 20 20 20 20 20 20 20 20 20 20 20 20	
3. Address & Phor PO Box 4289,	ES OIL & GAS  e No. of Opera Farmington, NM	tor 87499 (505) 326		8. Well Name & Number Jicarilla 150 #6  9. API Well No. 30-039-20240  10. Field and Pool Otero Cha/Blanco MV, BS Mesa Gal/Basin DI  11. County and State Rio Arriba Co, NM
			NOTICE, REPORT, OT	HER DATA
Type of Submis	s <b>sion</b> of Intent	<b>Type</b> Abandonment	of Action Change of	Plans
/ —		X Recompletion	n New Const	ruction
_X_ Subsec	quent Report	Plugging Ba Casing Repa	ck Non-Routi ir     Water Shu	ne Fracturing t.off
Final	Abandonment		sing Conversion	
13. Describe Pr	oposed or Comp	leted Operations		
<b>7-25-</b> 03 Wo	ork 2 3/8" tbg TOOH. Pump 800 KCl wtr. TIH, v	gal 15% HCl acros w pkr, set @ 30'.	8" tbg. TIH w/5 ½" ss Chacra interval	00 psi/15 min, OK.
		ol 20# linear gel	844' w/28 0.33" di , 1,548,500 SCF N2	ameter holes. Frac , 200,000# 20/40
7-29-03 Bl	ow well & CO. ' Establish circ	TOOH. TIH w/4 ¾": . Mill out CIBP @	4915'. Blow well	
	ow well & CO. '	TOOH. TIH w/242 j	OOH w/mill. TIH, b ts 2 3/8" 4.7# J-5 WH. RD. Rig relea	5 EUE tbg, landed @
		acra/Mesaverde/Ga ivision Order DHC		gle under New Mexico
14. I hereby ce	rtify hat the	foregoing is true	e and correct.	
Signed 1994	, Call	Title Regulate	ory Supervisor	Date 8/4/03
(This space for F		e Office <b>Division</b> zier <sub>Title</sub>	of Multi-Resource	SEP 1 6 2003
CONDITION OF APPR	OVAL, if any:			