<u>District I</u> 1625 N. French Dr , Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPER A								Report	☐ Final Report
Name of Company Burlington Resources, a wholly owned subsidiary of ConocoPhillips Company					Contact	Monica	Monica D. Johnson		
Address 3401 E. 30 th St., Farmington, NM 87402					Telephone No				
Facility Name San Juan 29-7 Unit #88A					Facility Type				PI # 30-039-21624
Surface Owner Private – Fidel Candelaria Mineral Owner Federal Lease No. SF-078903									
LOCATION OF RELEASE									
Unit Letter	Section	Township	Range	l l	th/South Line Feet from the East/West Line County				
C 6 T29N R7W 1050' North 900' West Rio Arrib									RIO AFFIDA
Latitude36.75902° Longitude107.61531°									
NATURE OF RELEASE									
		le oil / para						e Recovered – 17 BBL	
Source of Release: Stuffing box leak and separator dump controllers leak									nd Hour of Discovery 08 – 7:20 a.m.
Was Immedi	ate Notice (1	If YES, To Whom?			
☐ Yes ☐ No ☒ Not Required					Brandon Powell – OCD – via phone & email Herman Lujan – BLM – via email				
By Whom? Monica D. Johnson					Date and Hour – 1/25/08 – 4:00 p.m. PCUD JAN 29 109				
Was a Watercourse Reached?					If YES, Volume Impacting the Watercourse. OIL CONS. DIU.				
☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.*									NET O
The management was a supposed to the supposed									
Describe Cause of Problem and Remedial Action Taken.* A ConocoPhillips Company MSO (lease operator) discovered a crude oil / paraffin spill of approximately 25 BBL at the San Juan 29-7 Unit #88A on the morning of 1/23/08, due to a release from the dump controllers on the separator and also a stuffing box leak around the wellhead. This occurred due to the line from the wellhead to the tank freezing, and so the stuffing box leaked around the wellhead. It also appears that the well unloaded up the casing but the fire had gone out on the separator, thus spilling out of the dump controllers around the separator. Upon discovery, the well and pumping unit were shut in, and the impacted soil was fenced off. All spilled fluids remained on location, and 17 BBL was recovered by vacuum truck.									
Describe Area Affected and Cleanup Action Taken.* All spilled fluids remained on location, and 17 BBL was recovered by vacuum truck. Excavation of the remaining impacted soils for remediation is scheduled to begin on Monday, 1/28/08, with the soils being hauled offsite to a commercial landfarm. A final report will be sent upon the completion of remediation activities.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
Signature:	M	Mile). La	husen	OIL CONSERVATION DIVISION For: Cuar(se Perrin				
Printed Nam	e: <u>M</u>	onica D. Jo	/ ohnson		Approved by D	Approved by District Supervisor: Bol Hell Perrin			
Title:	Sen	ior Enviro	nmental S	scientist	Approval Date: 1-29-08 Expiration Date:				<u> </u>
E-mail Addr	ess: <u>monic</u>	a.johnson	@conocc	phillips.com	Conditions of A	Conditions of Approval:			ttached \square
Date: 1	/25/08		Phone: 5	05-326-9829					

^{*} Attach Additional Sheets If Necessary