

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

API 30-045-33992

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company BP America	Contact Larry Schlotterback
Address 200 Energy Court	Telephone No. (505) 326-9425
Facility Name LUDWICK LS 20E	Facility Type Gas Well

Surface Owner Federal	Mineral Owner	Lease No
---------------------------------	---------------	----------

LOCATION OF RELEASE

Unit Letter D	Section 29	Township 30N	Range 10W	Feet from the	LATITUDE 36.78801	Feet from the	LONGITUDE 107.91388	County San Juan
-------------------------	----------------------	------------------------	---------------------	---------------	-----------------------------	---------------	-------------------------------	---------------------------

Latitude 36.78801 Longitude -107.91388



NATURE OF RELEASE

Type of Release: NATURAL GAS	Volume of Release - 513 MCF	Volume Recovered - N/A
Source of Release: Separator	Date and Hour of Occurrence:	Date and Hour of Discovery 8/18/2007 - 13:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM & NMOCD	
By Whom? Larry Schlotterback	Date and Hour: 8/20/07 - 8:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* <div style="text-align: right;">RCVD AUG 28 '07 OIL CONS. DIV. DIST. 3</div>		

Describe Cause of Problem and Remedial Action Taken.* On August 18, 2007, a natural gas release was discovered on the Ludwick LS 20E and reported to the Animas Team Leader. A 2" Tee connecting pipe from the wellhead to the separator failed allowing gas to be released to the atmosphere. According to Optimizer reports, the Ludwick LS 20E began losing tubing pressure at 8:00 pm on 8/17/07 until shut-in at 1:00 pm on 8/18/07. Vented gas has been estimated at 513 MCF. The cause and integrity of the equipment is under investigation.

Describe Area Affected and Cleanup Action Taken.* NO FLUIDS impacted soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Larry Schlotterback		Approved by District Supervisor:  For: Charlie Perrin	
Title: Field Environmental Coordinator		Approval Date: 8-28-07	Expiration Date:
E-mail Address: schlln@bp.com		Conditions of Approval:	
Date: 8/23/07	Phone: 505-326-9425	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

n3P0726042265