


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003  
Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	BENSON-MONTIN-GREER DRILLING	Contact	MIKE DIMOND
Address	4900 College Blvd	Telephone No.	505-325-8874
Facility Name	EPCMU #35 (M-9)	Facility Type	Oil Well

Surface Owner	Cora Gomez	Mineral Owner	USA	API 30-039-23214	NM-78389X
---------------	------------	---------------	-----	------------------	-----------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	9	26N	1E	660'	South	660'	West	Rio Arriba

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release	Crude Oil	Volume of Release	15 Bbls	Volume Recovered	0
Source of Release	Well Head	1700 10/25 to 1000 10/27		Date and Hour of Discovery	10/27 1000 hr.
		9/25 10/27			9/27
Was Immediate Notice Given?	TO BLM & SFO FOREST <input type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
Required	Not required to NMOCD				
By Whom?	Mike Dimond				
Date and Hour	1215 on 10/27 9/27				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* Apparently a cow rubbed the wellhead and broke a nipple causing pumped oil to spill on ground. Well was shut-in and nipple replaced. Spill bermed and contained

Describe Area Affected and Cleanup Action Taken.\* Area affected is on the location for the well and the entrance road. Oil soaked about 5' deep and the contaminated soil is being excavated and removed to BMG COU Landfarm for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Mike Dimond</i>		OIL CONSERVATION DIVISION	
Printed Name: Mike Dimond		Approved by District Supervisor: <i>Brandon Russell</i> For: <i>Charlie Perrin</i>	
Title: President		Approval Date: 9/28/06	Expiration Date:
E-mail Address: mikedimond@bmgdrilling.com		Conditions of Approval:	
Date: 9/28/06	Phone: 505-325-8874	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

NBP0628439073