

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

# State of New Mexico

## Energy Minerals and Natural Resources Department


### Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141  
Originated 2/13/97



Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

#### Release Notification and Corrective Action

30 045 10944

#### OPERATOR

☐ Initial Report

☒ Final Report

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9841
Facility Name:	NORDHAUS 4A	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-078508
----------------	---------	----------------	---------	---------------	-------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County:
O	12	031N	009W	1000	South	1520	East	San Juan

#### NATURE OF RELEASE

Type of Release:	Condensate	Volume of Release:	35 BBLs.	Volume Recovered:	33 BBLs.
Source of Release:	Condensate Tank	Date and Hour of Occurrence:	4/20/2001	Date and Hour of Discovery:	4/20/2001
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?	Denny Foust		
By Whom?	Ed Hasely	Date and Hour:	4/20/2001 3:45:00 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	0		

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

The well produced more condensate than expected and the condensate overflowed. A vacuum truck recovered approximately 33 bbls of condensate.

Note: A message was left w/ Mark Kelly (BLM) on 4/23/01 at 7:45 am.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All fluids were contained inside the bermed area. The free liquids were recovered using a vacuum truck. The impacted soils (approx. 10 cy) were landfarmed on location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Ed Hasely</i>	OIL CONSERVATION DIVISION	
Printed Name:	Ed Hasely	Approved by:	<i>Denny Foust</i>
Title:	Environmental Representative	District Supervisor:	<i>for Frank Chavez</i>
Date:	4/23/01	Approval Date:	4/27/01
Phone:	(505) 326-9841 or <del>326-9842</del>	Expiration Date:	
Conditions of Approval:		Attached:	<input type="checkbox"/>

N 06P011057784