

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30 045 31931

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Burlington Resources	Contact	Ed Hasely
Address	P.O. Box 4289 Farmington NM 87499	Telephone No.	(505) 326-9700
Facility Name	TURNER B COM	250S	Facility Type Gas Well
Surface Owner	State	Mineral Owner	State
		Lease No.	E-2757-4-NM

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	02	030N	009W	815	South	725	West	San Juan

NATURE OF RELEASE

Type of Release	Drilling Fluids - Fresh Water	Volume of Release	40 BBLs	Volume Recovered	38 BBLs.
Source of Release	Wellhead	Date and Hour of Occurrence	1/21/2005 8:30:00 PM	Date and Hour of Discovery	1/21/2005 8:30:00 PM
Was Immediate Notice Given?	☒ Yes ☐ No ☐ Not Required	If YES, To Whom?	Charlie Perrin		
By Whom?	Larry Dillon	Date and Hour	1/22/2005		
Was a Watercourse Reached?	☐ Yes ☒ No	If YES, Volume Impacting the Watercourse			

If a Watercourse was Impacted, Describe Fully.*

NA

Describe Cause of Problem and Remedial Action Taken.*

While tripping out of the hole, the well started to unload. Approximately 40 bbls of drilling fluid / fresh water flowed out of the BOPs before the flow could be diverted to the reserve pit.

Describe Area Affected and Cleanup Action Taken.*

The flow was diverted to the reserve pit. The BOP's were closed and a heavy mud was circulated to control the well. All released fluids were contained on location and were eventually forced to the reserve pit.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Ed Hasely	Approved by District Supervisor: <i>Denny Fount</i> for Charlie Perrin acts		
Title: Environmental Representative	Approval Date: 1/27/05	Expiration Date:	
E-mail Address: lhasely@br-inc.com or gwurtz@br-inc.com	Conditions of Approval:	Attached	
Date: 1/25/05 Phone: (505) 326-9841 or 9537	☐		

* Attach Additional Sheets If Necessary

n DGF 0502428091

Burlington Resources

MEMORANDUM

TO: WELL FILE

DATE

1/22/05

FROM: REGULATORY SPECIALIST
AREA OF WELL

Jon Clark

RE: NOTIFICATION OF CHANGE OF PLANS

NOTIFIED: BLM, FARMINGTON-599-8900

BLM, DURANGO-970-247-4082

✓ NMOCD, AZTEC-334-6178

Charlie Brown 334-3902

CO O&G, DURANGO-970-259-4587

CO O&G, DENVER-303-239-3700

OTHER

ENGINEER: Larra Dilap

TYPE OF CHANGE well unblock

WELL NAME Turner Dam 2503

SEC 2, TWN 30 N, RNG 9 W 705 FWL

LEASE NUMBER E-10889-30

API# 30-045-31931

DETAILS OF CALL: Bear cat #4

OPE coal well was 3104' deep. They were 400' from the TD. Well Surge broke. It broke unblock on them. Got back to btm & under control. Going back to btm. Took 400' to retrieve screen. Took 100' more. Well blew hole. Making a lot of water. mud went off location a little.

FOLLOW UP NEEDED:

2 spots where they need to fix liners (water level below repairs)

✓ SUNDRY

Bennett to fix & cleanup location

OTHER

Follow up w/ hard copy

Call Ed Monday
Dane Clark

Copy of logs Monday

Let Dianne know Monday also