

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FEB 11 2010

FORM APPROVED
OMB No 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
Contract 111
6. Indian, Allottee or Tribe Name
Jicarilla

SUBMIT IN TRIPLICATE – Other instructions on page 2.

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
D.J. Simmons, Inc.

3a. Address
1009 Ridgeway Place, Ste 200, Farmington, NM 87401

3b. Phone No. (include area code)
505-326-3753

4. Location of Well (Footage, Sec., T, R., M., or Survey Description)
1950' FSL, 1650' FWL
Sec 6, T24N, R4W

7. If Unit of CA/Agreement, Name and/or No

8. Well Name and No
Jicarilla H 112

9. API Well No
30-039-22252

10. Field and Pool or Exploratory Area
Otero Chacra

11. Country or Parish, State
Rio Arriba, NM

12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input checked="" type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

- 1 - set CIBP w/ Zsx cement @ 6100' +/- to permanently abandon lower zones: Gallup, Dakota
- 2 - load hole and test casing to 500 PSI
- 3 - run CBL from stage tool at 3870' to TOC
- 4 - perf Chacra over 3739' to 3869' at select intervals
- 5 - sand water frac Chacra
- 6 - clean up
- 7 - return to production

Detailed engineering will be done prior to recompletion and will be included with subsequent report.

RCVD FEB 17 '10
OIL CONS. DIV.

DIST. 3

W 2-5-10

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Laura Tucker

Title Agent

Signature

Date

2-5-10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Original Signed: Stephen Mason

Title

Date

FEB 16 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)

NMOCD