RECEIVED

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

MAR 08 2010

	Sundry Notices and Report	s on Wells	3		Farmington Field Office
				5.	Lease Number
1 Trum	e of Well			6.	SF-078876
				0.	If Indian, All. or Tribe Name
	GAS				Tibe Name
				7.	Unit Agreement Name
2. Nan	ne of Operator			· •	Canyon Largo Unit
	JRLINGTON				,, <u></u>
	RESOURCES OIL &	CAC COMBANN I B			
	TESOUNCES OIL &	GAS CUMPANT LP		– 8.	Well Name & Number
3. Address & Phone No. of Operator				– 0.	Canyon Largo Unit 16
J. Auu	iress & I holle 100. of Operat	.01			Canyon Largo Cint 10
PO	Box 4289, Farmington, NM	87499 (505) 326-9700		9.	API Well No.
		•			30-039-60052
4. Location of Well, Footage, Sec., T, R, M Surf: Unit A (NENE), 810' FNL & 1180' FEL, Section 30, T25N, R7W, NMPM					
				10.	Field and Pool
					Ballard PC/Basin FC
				11.	County and State
					Rio Arriba Co., NM
		TO INDICATE NAT	URE OF NOTICE, REPORT, O		DATA Other Road Inaccessible
		Recompletion	New Construction		RCVD MAR 16'10
	Subsequent Report	Plugging	Non-Routine Fracturing		OIL CONS. DIV.
	E' I Al I	Casing Repair	Water Shut off		
セ -	Final Abandonment	Altering Casing	Conversion to Injection		D151.3
in respon 5/1/2010.		ived March 4, 2010. Bocation is inaccessible.	Surlington Resources would like to With the current weather condition Cerva to production		
14. I her	reby-certify that the foregoin	ng is true and correct.	•		
01	State	_	Diamin Danier Title Coeff	D1-4-	Tasknisian Data 2/5/10
Signed	your selection	2	Rhonda Rogers Title Staff	Regulate	ory Technician Date 3/5/10
(This spa	ace for Federal or State Office	use)			MAR 1 1 2010
					Date
	TION OF APPROVAL, if any				



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Field Office 1235 La Plata Highway, suite A Farmington, New Mexico 87401

IN REPLY REFER TO

NMSF-078876 et al (WC) 3162.3-2 (21110)

Ms. Sharon Zubrod Burlington Resources Oil & Gas Co. PO Box 4289 Farmington, NM 87499 CONOCO PHILLIPS

March 2, 2010

MAH - 4 2010

FARMINGTON NEW MEYICO

Dear Ms. Zubrod:

Our records indicate that you are the operator of the following wells:

1) No. 16 Canyon Largo Unit located 810' FNL & 1180' FEL sec. 30, T. 25 N., R. 7 W., Rio Arriba County, New Mexico, Lease NMSF-078876. Well has not produced since November 2008.

2) No. 62 San Juan 27-5 Unit located 940' FNL & 765' FEL sec. 6, T. 27 N., R. 5 W., Rio Arriba County, New Mexico, Lease NMSF-079393. Well has not produced since November 2008.

Title 43 CFR Section 3162.3-4 requires that the lessee shall promptly plug and abandon, condition as a service well, or condition as a water well, any well on a lease that is not used or useful for the purpose of the lease. Accordingly, you are required to advise this office by Sundry Notice within 30 calendar days of your intent to perform one of the following: a) Condition the well to a useful function, b) Temporarily abandon the well, c) Continued shut-in status, d) Permanently plug and abandon the well.

See attached General Requirements for Non-Producing wells on Federal leases.

The 30 calendar days commences upon receipt of this letter or seven days from the date it is mailed, whichever is less. Failure to comply within the 30 calendar days may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 *et seq*.

If you have any questions, please contact Stephen Mason with this office at (505) 599-6364.

Sincerely,

Stephen Mason

Petroleum Engineer, Petroleum Management Team

1 Attachment