


	The same of the sa					
united states Form 3160 DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT		FORM APPROVED Budget Bureau No. 1004-0135				
SUNDRY NOTICE AND Do not use this form for proposals to drill or to deepen or	5. Lease Designation and Serial No. SF-078768					
TO DRILL" for perm	6. If Indian, Allottee or Tribe Name					
SUBMIT IN T	7. If Unit or CA, Agreement Designation ROSA UNIT					
Type of Well Oil Well X Gas Well Other	8. Well Name and No. ROSA UNIT #343A					
Name of Operator WILLIAMS PRODUCTION COMPANY	9. API Well No. 30-039-30144					
3. Address and Telephone No. PO BOX 3102 MS 25-4, TULSA, OK 74101 (10. Field and Pool, or Exploratory Area BASIN FRUITLAND COAL					
 Location of Well (Footage, Sec., T., R., M., or Survey Description) 1830' FSL, 1195' FEL, NE/4 SE/4, SEC 26, T31N, R05W 		1. County or Parish, State RIO ARRIBA, NM				
CHECK APPROPRIA	TE BOX(s) TO INDICATE NATURE OF NOTICE, REP	ORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE O					
Notice of Intent	Abandonment	Change of Plans				
Ξ Subsequent Report	Recompletion Plugging Back	New Construction Non-Routine Fracturing				
	Casing Repair	Water Shut-Off				
Final Abandonment	Altering Casing X Other TUBING REPAIR	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report				
13. Describe Proposed or Completed Operations (C directionally drilled, give subsurface locations	and Log form.) Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*					
<u>04-23-2010</u> MIRU, TOH w/ rods & pump, ND B-1 adapte	er, NUBOP's, pull tubing hanger & 1 joint, SIV	V, SDFW, resume operations on 4/26/10.				
04-26-2010 Bd to tk, remove chem inj line, RU Tubascope red band, notify engineer, run back w/ yellow		llow band, 46 joints bl band, 23 joints green & ble & 32 joints yellow band, SIW, SDFN.				
O4-27-2010 Bd to tk, spot in tubing, tally & PU 2 7/8" yell as follows: 103 joints, 2.28" F-Nipple @ 3278 Tubascope, received 74 joints yellow band f/ Tubascope, NDBOP's, NU B-1 adapter, TIH box, rods ran as follows: 22' PR, 8', 4', 2' pony pump & press tubing to 500# 15 min, no lk of	", mud anchor @ 3305', FC perfs 3244'-3331' Tubascope, ran 69 joints 2 7/8" 6.5# J55 EUE w/ pump & rods, changed out 110 - 3/4" rod be r rods, 127 - 3/4 rods, 3 - 1 1/4" sinker bars, 2.	LD 69 bad joints in derrick & ship to yellow band in hole, ship 3 joints back to exes, install snap on guides, one above every				
14. I hereby certify that the foregoing is true and co	orrect /	DIST. 3				
Signed Agent Lypers	Title Engineering Technician II Di	ate May 7, 2010 AGGEPTED FOR RECORL				
(This space for Federal or State office use)		MAY 1 4 2010				
Approved by	Title	Date FARMINGTON FIELD OFFICE				
Conditions of approval, if any:		LATINITION OF LIEU OF LICE				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

ROSA UNIT #343A BASIN FRUITLAND COAL



Hole Sıze	Casing	Cement	Volume	Top of Cmt
12-1/4"	9-5/8", 36#	188 sxs	265 cu.ft.	Surface
8-3/4"	7", 23#	625 sxs	1271 cu.ft.	Surface
6-1/4"	5-1/2", 17#	Did Not Cmt		