



New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson
Governor

Jon Goldstein
Cabinet Secretary

Jim Noel
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



June 18, 2010

XTO Energy Inc.
382 CR 3100
Aztec, NM 87410

DENIAL OF APPLICATION FOR PERMIT TO DRILL, DEEPEN OR PLUG BACK

Re: XTO Energy Inc. , OGRID 5380
Huerfano Unit # 319, 30-045-35100, K-14-25N-9W, San Juan County, NM

Dear Operator:

The Oil Conservation Division (OCD) **denies** your application(s) for permit(s) to drill, deepen or plug back the wells identified above because your company is out of compliance with 19.15.5.9(A) NMAC [Part 5.9(A)]. See 19.15.14.10(A) NMAC.

Your company is out of compliance with Part 5.9(A) on the following ground(s):

- ☒ **Financial assurances.** Your company is in violation of the financial assurance requirements for well plugging set out in 19.15.8.9 NMAC. See 19.15.5.9(A)(1) NMAC. Specifically, your company has not posted the single-well financial assurances required for state or fee wells which have been inactive for more than two years. The wells requiring single-well financial assurances are identified in the attached sheet.
- ☐ **Corrective action.** Order _____, issued on _____ after notice and hearing, found your company to be in violation of an order requiring corrective action. See 19.15.5.9(A)(2) NMAC.
- ☐ **Unpaid penalties.** Your company has not paid the penalties assessed against your company in _____, issued on _____. More than 70 days have passed since the issuance of the order assessing the penalty. See 19.15.5.9(A)(3) NMAC.
- ☐ **Inactive wells.** According to the attached inactive well list, your company has too many wells in violation of the inactive well rule (19.15.25.8 NMAC) that are not subject to an inactive well agreed




June 18, 2010

Page 2

compliance order. See 19.15.5.9(A)(4) NMAC. As an operator of ____ wells, your company may have no more than ____ wells in violation of the inactive well rule. Your company has ____ wells in violation of the inactive well rule. In addition,

I have enclosed an information sheet explaining the requirements of Part 5.9. You may re-submit your request after your company has returned to compliance with Part 5.9.

Respectfully yours,



Daniel Sanchez, Compliance and Enforcement Manager

Ec: Mark Fesmire, Division Director, Santa Fe
Theresa Duran-Saenz, Legal Assistant, Santa Fe
Larry "Buddy" Hill, District 1 Supervisor
Randy Dade, District 2 Supervisor
Charlie Perrin, District 3 Supervisor
Ed Martin, District 4 Supervisor
Amy H. Vermersch, Aztec Compliance Officer

Inactive Well Additional Financial Assurance Report

5380 XTO ENERGY, INC

Total Well Count: 3231

Printed On: Friday, June 18 2010

Property	Well Name	Lease Type	ULSTR	OCD Unit Letter	API	Well Type	Last Prod/Inj	Inactive Additional Bond Due	Measured Depth	Required Bond Amount	Bond Required Now	Bond In Place	In Violation
300706	A B REEVES #001	P	L-29-20S-37E	L	30-025-06277	G	04/2010	05/01/2012	3846	8846		0	
	A B REEVES #003	P	G-29-20S-37E	G	30-025-28436	G	04/2010	05/01/2012	3700	8700		0	
	A B REEVES #004	P	J-29-20S-37E	J	30-025-31034	G	04/2010	05/01/2012	3778	8778		0	
300650	A L CHRISTMAS NCT C #007	P	H-18-22S-37E	H	30-025-10350	O	04/2010	05/01/2012	3700	8700		0	
	A L CHRISTMAS NCT C #009	P	G-18-22S-37E	G	30-025-25499	O	04/2010	05/01/2012	6750	11750		0	
	A L CHRISTMAS NCT C #010	P	F-18-22S-37E	F	30-025-25530	O	04/2010	05/01/2012	6710	11710		0	
	A L CHRISTMAS NCT C #011	P	H-18-22S-37E	H	30-025-25594	O	04/2010	05/01/2012	6700	11700		0	
	A L CHRISTMAS NCT C #012	P	2-18-22S-37E	E	30-025-25624	O	04/2010	05/01/2012	6700	11700		0	
	A L CHRISTMAS NCT C #013	P	A-18-22S-37E	A	30-025-25634	O	04/2010	05/01/2012	6710	11710		0	
	A L CHRISTMAS NCT C #014	P	1-18-22S-37E	D	30-025-25645	O	02/2009	03/01/2011	6700	11700		0	
	A L CHRISTMAS NCT C #015	P	3-18-22S-37E	L	30-025-25657	O	07/2009	08/01/2011	6700	11700		0	
	A L CHRISTMAS NCT C #016	P	4-18-22S-37E	M	30-025-25670	O	04/2010	05/01/2012	6700	11700		0	
	A L CHRISTMAS NCT C #017	P	1-18-22S-37E	D	30-025-30649	G	04/2010	05/01/2012	3798	8798		8800	
306474	A L ELLIOTT B #005E	F	P-10-29N-09W	P	30-045-25594	G	04/2010		7082			0	
	A L ELLIOTT B #006E	F	D-10-29N-09W	D	30-045-25716	G	04/2010		7040			0	
22747	A R HUBBELL A #001	F	K-30-28N-10W	K	30-045-07155	G	04/2010		1985			0	
22647	ABRAMS GAS COM A #001	P	I-26-29N-10W	I	30-045-07821	G	12/2008	01/01/2011	1959	6959		0	
22648	ABRAMS GAS COM C #001	P	F-25-29N-10W	F	30-045-07880	G	05/2009	06/01/2011	1963	6963		0	
22649	ABRAMS GAS COM D #001	P	I-29-29N-10W	I	30-045-07822	G	12/2009	01/01/2012	1875	6875		0	
22650	ABRAMS GAS COM E #001	P	I-30-29N-10W	I	30-045-07815	G	04/2010	05/01/2012	6383	11383		0	
	ABRAMS GAS COM E #001E	F	4-30-29N-10W	M	30-045-24733	G	04/2010		6475			0	
23069	ABRAMS GAS COM G #001	P	I-30-29N-10W	I	30-045-24955	G	04/2010	05/01/2012	2953	7953		0	
23157	ABRAMS GAS COM J #001	P	D-25-29N-10W	D	30-045-25898	G	04/2010	05/01/2012	4590	9590		0	
23158	ABRAMS GAS COM M #001	P	I-26-29N-10W	I	30-045-26166	G	06/2009	07/01/2011	3150	8150		0	
22651	ABRAMS J #001	P	I-29-29N-10W	I	30-045-25521	O	04/2010	05/01/2012	5783	10783		0	
22652	ABRAMS L #001	P	M-26-29N-10W	M	30-045-25670	O	04/2010	05/01/2012	5940	10940		0	
	ABRAMS L #001A	P	I-26-29N-10W	I	30-045-25616	G	04/2010	05/01/2012	5900	10900		0	
32687	ADAIR #001	P	G-29-29N-10W	G	30-045-31805	G	04/2010	05/01/2012	1984	6984		0	
	ADAIR #002	P	C-29-29N-10W	C	30-045-31804	G	04/2010	05/01/2012	1958	6958		0	
303332	ALBRIGHT #020	P	H-27-29N-10W	H	30-045-27220	G	08/2009	09/01/2011	3026	8026		0	
30309	ALICE BOLACK #002	F	I-21-27N-11W	I	30-045-06369	G	04/2010		2095			0	
	ALICE BOLACK #005	F	K-9-27N-11W	K	30-045-06661	G	04/2010		2036			0	
	ALICE BOLACK #006	F	C-9-27N-11W	C	30-045-06745	G	04/2010		2032			0	
	ALICE BOLACK #008	F	6-9-27N-11W	I	30-045-06663	G	04/2010		2037			0	
	ALICE BOLACK #011	F	A-16-27N-11W	A	30-045-06584	G	04/2010		2146			0	
	ALICE BOLACK #013	F	7-15-27N-11W	K	30-045-06488	G	04/2010		2048			0	
	ALICE BOLACK #014	F	I-16-27N-11W	I	30-045-06498	G	08/2009		2880			0	
300651	AMERICAN NATIONAL KEOHANE COM #001	P	C-18-19S-37E	C	30-025-05630	G	04/2010	05/01/2012	3700	8700		0	
	AMERICAN NATIONAL KEOHANE COM #002	P	G-18-19S-37E	G	30-025-30814	G	04/2010	05/01/2012	3650	8650		0	
	AMERICAN NATIONAL KEOHANE COM #003	S	2-18-19S-37E	E	30-025-33391	G	04/2010	05/01/2012	3682	8682		0	
304672	AMOCO A #001R	P	H-21-30N-12W	H	30-045-30785	G	08/2009	09/01/2011	1960	6960		0	
	AMOCO A #002	F	D-21-30N-12W	D	30-045-30643	G	04/2010		2010			0	
22653	ANDERSON GAS COM A #001	P	C-28-29N-10W	C	30-045-24954	G	04/2010	05/01/2012	3207	8207		0	
23159	ANDERSON GAS COM B #001	P	K-28-29N-10W	K	30-045-26168	G	08/2009	09/01/2011	3060	8060		0	
33116	APACHE FEDERAL #001	J	N-17-24N-05W	N	30-039-05448	G	04/2010		2237			0	
	APACHE FEDERAL #005	J	H-18-24N-05W	H	30-039-05497	G	09/2009		2325			0	
	APACHE FEDERAL #006	J	G-7-24N-05W	G	30-039-05596	G	04/2010		2445			0	
	APACHE FEDERAL #007	J	G-17-24N-05W	G	30-039-05483	G	10/2009		2475			0	
	APACHE FEDERAL #008	J	D-8-24N-05W	D	30-039-05610	G	04/2010		7045			0	
	APACHE FEDERAL #008E	F	A-8-24N-05W	A	30-039-23040	G	04/2010		6900			0	
	APACHE FEDERAL #010	J	J-18-24N-05W	J	30-039-05477	G	04/2010		6794			0	
	APACHE FEDERAL #010E	J	N-18-24N-05W	N	30-039-22675	G	04/2010		6673			0	
	APACHE FEDERAL #011E	J	L-8-24N-05W	L	30-039-22673	G	04/2010		6798			0	
	APACHE FEDERAL #013	J	J-7-24N-05W	J	30-039-05566	G	04/2010		6774			0	
	APACHE FEDERAL #013E	J	K-7-24N-05W	K	30-039-22672	G	04/2010		6765			0	
	APACHE FEDERAL #014	J	L-18-24N-05W	D	30-039-05514	G	04/2010		6760			0	
	APACHE FEDERAL #015	J	I-7-24N-05W	D	30-039-60125	G	04/2010		6878			0	
	APACHE FEDERAL #016	J	J-7-24N-05W	J	30-039-29678	G	04/2010		2360			0	
	APACHE FEDERAL #017	J	F-18-24N-05W	F	30-039-29679	G	04/2010		2300			0	
38005	ARBOR #002	N	P-26-25N-10W	P	30-045-35031	G			Unknown			0	
	ARBOR #021H	N	D-26-25N-10W	D	30-045-35033	G	04/2010		5696			0	
	ARBOR #022H	F	L-26-25N-10W	L	30-045-35029	G			5505			0	
303333	ARMENTA #001	P	H-27-29N-10W	H	30-045-07850	G	02/2008	03/01/2010	1925	6925	Y	6925	

22654	ARMENTA GAS COM A #001	P	D-27-29N-10W	D	30-045-07926	G	04/2010	05/01/2012	1920	6920		0
22587	ARMENTA GAS COM C #001A	P	H-27-29N-10W	H	30-045-25671	O	12/2008	01/01/2011	5925	10925		0
	ARMENTA GAS COM C #001E	P	C-27-29N-10W	C	30-045-23856	G	04/2010	05/01/2012	6564	11564		0
	ARMENTA GAS COM C #001R	F	P-22-29N-10W	P	30-045-32193	G	04/2010		7025			0
29078	ARMENTA GAS COM G #001	P	H-27-29N-10W	H	30-045-30932	G	12/2008	01/01/2011	2074	7074		0
	ARMENTA GAS COM G #002Y	P	P-27-29N-10W	P	30-045-32964	G	04/2010	05/01/2012	1882	6882		0
34232	ARMJO TRUST #001	P	P-27-10N-01W	P	30-001-20010	G			908			0
304995	ARNIE #001	F	B-33-30N-13W	B	30-045-29667	G	04/2010		1625			0
	ARNIE #001T	F	E-33-30N-13W	E	30-045-32156	G	04/2010		1790			0
	ARNIE #002	F	E-25-30N-13W	E	30-045-29669	G	04/2010		2005			0
	ARNIE #003	F	G-25-30N-13W	G	30-045-29688	G	04/2010		2070			0
	ARNIE #004	F	A-25-30N-13W	A	30-045-31008	G	04/2010		1950			0
	ARNIE #004T	F	F-25-30N-13W	F	30-045-32167	G	08/2009		1930			0
300655	ARNOTT RAMSAY NCT D #003	S	F-33-21S-36E	F	30-025-04884	G	04/2010	05/01/2012	3900	8900		0
	ARNOTT RAMSAY NCT D #004	S	E-33-21S-36E	E	30-025-04885	O	04/2010	05/01/2012	3909	8909		0
	ARNOTT RAMSAY NCT D #006	S	K-33-21S-36E	K	30-025-04887	O	11/1992	12/01/1994	3909	8909	Y	8909
	ARNOTT RAMSAY NCT D #007	S	M-33-21S-36E	M	30-025-04888	O	04/2010	05/01/2012	3856	8856		0
	ARNOTT RAMSAY NCT D #008	S	N-33-21S-36E	N	30-025-04889	O	04/2010	05/01/2012	3870	8870		0
	ARNOTT RAMSAY NCT D #009	S	L-33-21S-36E	L	30-025-04890	O	04/2010	05/01/2012	3870	8870		8870
	ARNOTT RAMSAY NCT D #010	S	O-33-21S-36E	O	30-025-04891	O	04/2010	05/01/2012	3880	8880		0
	ARNOTT RAMSAY NCT D #012	S	J-33-21S-36E	J	30-025-04893	G	04/2010	05/01/2012	3900	8900		0
	ARNOTT RAMSAY NCT D #015	S	B-33-21S-36E	B	30-025-26167	G	04/2010	05/01/2012	3950	8950		0
300649	ARROWHEAD GRAYBURG UNIT #106	S	G-25-21S-36E	G	30-025-23324	I	04/2010	05/01/2012	3900	8900		0
	ARROWHEAD GRAYBURG UNIT #107	S	H-25-21S-36E	H	30-025-21620	O	04/2010	05/01/2012	5225	10225		0
	ARROWHEAD GRAYBURG UNIT #108	P	I-25-21S-36E	I	30-025-23949	O	04/2010	05/01/2012	3899	8899		0
	ARROWHEAD GRAYBURG UNIT #113	F	M-25-21S-36E	M	30-025-31519	I	04/2010		3945			0
	ARROWHEAD GRAYBURG UNIT #114	S	N-25-21S-36E	N	30-025-24189	O	07/1998	08/01/2000	6002	11002	Y	11002
	ARROWHEAD GRAYBURG UNIT #115	P	O-25-21S-36E	O	30-025-23939	I	04/2010	05/01/2012	6000	11000		0
	ARROWHEAD GRAYBURG UNIT #116	P	P-25-21S-36E	P	30-025-23995	O	08/1997	09/01/1999	3930	8930	Y	8930
	ARROWHEAD GRAYBURG UNIT #119	S	C-36-21S-36E	C	30-025-04932	I	04/2010	05/01/2012	3846	8846		0
	ARROWHEAD GRAYBURG UNIT #120	S	D-36-21S-36E	D	30-025-29093	O	04/2010	05/01/2012	6930	11930		0
	ARROWHEAD GRAYBURG UNIT #121	S	A-35-21S-36E	A	30-025-04914	I	04/2010	05/01/2012	3975	8975		0
	ARROWHEAD GRAYBURG UNIT #124	S	G-35-21S-36E	G	30-025-04916	I	04/2010	05/01/2012	4025	9025		0
	ARROWHEAD GRAYBURG UNIT #125	S	H-35-21S-36E	H	30-025-31433	O	02/2008	03/01/2010	3953	8953	Y	8953
	ARROWHEAD GRAYBURG UNIT #126	S	E-36-21S-36E	E	30-025-04930	I	04/2010	05/01/2012	3910	8910		0
	ARROWHEAD GRAYBURG UNIT #127	S	F-36-21S-36E	F	30-025-04933	O	04/2010	05/01/2012	3830	8830		0
	ARROWHEAD GRAYBURG UNIT #128	S	G-36-21S-36E	G	30-025-24105	I	04/2010	05/01/2012	6791	11791		0
	ARROWHEAD GRAYBURG UNIT #131	S	J-36-21S-36E	J	30-025-31247	O	02/1997	03/01/1999	3898	8898	Y	9500
	ARROWHEAD GRAYBURG UNIT #132	S	K-36-21S-36E	K	30-025-04929	I	04/2010	05/01/2012	3944	8944		0
	ARROWHEAD GRAYBURG UNIT #133	S	L-36-21S-36E	L	30-025-04939	I	04/2010	05/01/2012	3852	8852		0
	ARROWHEAD GRAYBURG UNIT #134	S	I-35-21S-36E	I	30-025-04920	I	04/2010	05/01/2012	3930	8930		0
	ARROWHEAD GRAYBURG UNIT #135	S	J-35-21S-36E	J	30-025-04917	O	04/2010	05/01/2012	4000	9000		0
	ARROWHEAD GRAYBURG UNIT #138Y	P	N-35-21S-36E	N	30-025-32827	O	04/2010	05/01/2012	4068	9068		0
	ARROWHEAD GRAYBURG UNIT #139	S	O-35-21S-36E	O	30-025-31305	I	04/2010	05/01/2012	3990	8990		0
	ARROWHEAD GRAYBURG UNIT #140	S	P-35-21S-36E	P	30-025-04921	O	04/2010	05/01/2012	3860	8860		0
	ARROWHEAD GRAYBURG UNIT #141	S	M-36-21S-36E	M	30-025-04938	I	04/2010	05/01/2012	3895	8895		0
	ARROWHEAD GRAYBURG UNIT #142	S	N-36-21S-36E	N	30-025-04928	O	02/2009	03/01/2011	3820	8820		0
	ARROWHEAD GRAYBURG UNIT #143	S	O-36-21S-36E	O	30-025-04940	I	04/2010	05/01/2012	3880	8880		0
	ARROWHEAD GRAYBURG UNIT #144	S	P-36-21S-36E	P	30-025-31633	O	02/1997	03/01/1999	4500	9500	Y	9500
	ARROWHEAD GRAYBURG UNIT #148	F	3-1-22S-36E	C	30-025-31393	I	04/2010		3915			0
	ARROWHEAD GRAYBURG UNIT #149	F	4-1-22S-36E	D	30-025-08733	O	04/2010		3850			0
	ARROWHEAD GRAYBURG UNIT #150	S	1-2-22S-36E	A	30-025-08741	I	04/2010	05/01/2012	3845	8845		0
	ARROWHEAD GRAYBURG UNIT #151	S	2-2-22S-36E	B	30-025-08738	I	04/2010	05/01/2012	3847	8847		0
	ARROWHEAD GRAYBURG UNIT #155	S	F-2-22S-36E	F	30-025-31417	O	04/2010	05/01/2012	4020	9020		0
	ARROWHEAD GRAYBURG UNIT #156	S	G-2-22S-36E	G	30-025-08748	I	04/2010	05/01/2012	3960	8960		0
	ARROWHEAD GRAYBURG UNIT #157	S	H-2-22S-36E	H	30-025-08740	O	04/2010	05/01/2012	3860	8860		0
	ARROWHEAD GRAYBURG UNIT #158	F	E-1-22S-36E	E	30-025-08721	I	04/2010		3825			0
	ARROWHEAD GRAYBURG UNIT #159	F	F-1-22S-36E	F	30-025-08723	I	04/2010		3810			0
	ARROWHEAD GRAYBURG UNIT #160	F	G-1-22S-36E	G	30-025-24272	I	04/2010		6860			0
	ARROWHEAD GRAYBURG UNIT #166	F	J-1-22S-36E	J	30-025-08724	O	04/2010		3802			0
	ARROWHEAD GRAYBURG UNIT #167	P	K-1-22S-36E	K	30-025-08728	I	04/2010	05/01/2012	3886	8886		0
	ARROWHEAD GRAYBURG UNIT #168	P	L-1-22S-36E	L	30-025-08727	O	04/2010	05/01/2012	3790	8790		0
	ARROWHEAD GRAYBURG UNIT #169	S	1-2-22S-36E	I	30-025-08739	I	04/2010	05/01/2012	3840	8840		0
	ARROWHEAD GRAYBURG UNIT #170	S	J-2-22S-36E	J	30-025-31435	O	04/2010	05/01/2012	3950	8950		0
	ARROWHEAD GRAYBURG UNIT #171	S	K-2-22S-36E	K	30-025-31734	I	04/2010	05/01/2012	3995	8995		0
	ARROWHEAD GRAYBURG UNIT #172	S	L-2-22S-36E	L	30-025-08735	O	02/1997	03/01/1999	3820	8820	Y	8820
	ARROWHEAD GRAYBURG UNIT #174	S	N-2-22S-36E	N	30-025-31304	O	04/2010	05/01/2012	4090	9090		0
	ARROWHEAD GRAYBURG UNIT #175	S	O-2-22S-36E	O	30-025-08745	I	04/2010	05/01/2012	3976	8976		0
	ARROWHEAD GRAYBURG UNIT #176	S	P-2-22S-36E	P	30-025-08742	O	04/2010	05/01/2012	3816	8816		0

NORTH VACUUM ABO EAST UNIT #007	S	F-18-17S-35E	F	30-025-24145	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO EAST UNIT #008	S	H-18-17S-35E	H	30-025-24125	I	04/2010 05/01/2012	8910	13910	0
NORTH VACUUM ABO EAST UNIT #009	S	J-18-17S-35E	J	30-025-24262	I	04/2010 05/01/2012	12515	17515	0
NORTH VACUUM ABO EAST UNIT #010	S	3-18-17S-35E	L	30-025-24519	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO EAST UNIT #011	S	N-18-17S-35E	N	30-025-23918	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO EAST UNIT #012	S	2-18-17S-35E	E	30-025-29383	O	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO EAST UNIT #013	S	4-18-17S-35E	M	30-025-29384	O	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO EAST UNIT #014	S	4-7-17S-35E	H	30-025-29385	O	05/2008 06/01/2010	8800	13800	Y 0
NORTH VACUUM ABO EAST UNIT #015	S	G-18-17S-35E	G	30-025-29386	O	04/2010 05/01/2012	8925	13925	0
NORTH VACUUM ABO EAST UNIT #016	S	O-7-17S-35E	O	30-025-29387	O	04/2010 05/01/2012	8950	13950	0
NORTH VACUUM ABO EAST UNIT #017	S	C-18-17S-35E	C	30-025-29388	O	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO EAST UNIT #018	S	K-18-17S-35E	K	30-025-29389	O	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO EAST UNIT #019	S	K-7-17S-35E	K	30-025-29390	O	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO EAST UNIT #020	S	I-7-17S-35E	I	30-025-29391	O	04/2010 05/01/2012	9000	14000	0
NORTH VACUUM ABO EAST UNIT #021	S	A-18-17S-35E	A	30-025-29392	O	04/2010 05/01/2012	8975	13975	0
NORTH VACUUM ABO EAST UNIT #022	S	O-18-17S-35E	O	30-025-29393	O	04/2010 05/01/2012	8900	13900	0
NORTH VACUUM ABO EAST UNIT #023	S	N-7-17S-35E	N	30-025-30207	O	04/2010 05/01/2012	8950	13950	0
301587 NORTH VACUUM ABO UNIT #098	S	J-26-17S-34E	J	30-025-20320	I	02/2009 03/01/2011	11660	16660	0
NORTH VACUUM ABO UNIT #109	S	N-24-17S-34E	N	30-025-21617	I	04/2010 05/01/2012	12470	17470	0
NORTH VACUUM ABO UNIT #112	S	D-25-17S-34E	D	30-025-21751	I	04/2010 05/01/2012	10230	15230	0
NORTH VACUUM ABO UNIT #116	S	L-24-17S-34E	L	30-025-21808	I	04/2010 05/01/2012	10436	15436	0
NORTH VACUUM ABO UNIT #117	S	P-23-17S-34E	P	30-025-21828	I	04/2010 05/01/2012	10414	15414	0
NORTH VACUUM ABO UNIT #118	S	F-26-17S-34E	F	30-025-23526	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #119	S	F-24-17S-34E	F	30-025-22001	I	04/2010 05/01/2012	12391	17391	0
NORTH VACUUM ABO UNIT #121	S	L-13-17S-34E	L	30-025-22101	I	04/2010 05/01/2012	10550	15550	0
NORTH VACUUM ABO UNIT #122	S	I-3-17S-34E	I	30-025-22102	O	04/2010 05/01/2012	10840	15840	0
NORTH VACUUM ABO UNIT #124	S	P-14-17S-34E	P	30-025-22386	I	04/2010 05/01/2012	10565	15565	0
NORTH VACUUM ABO UNIT #128	S	H-23-17S-34E	H	30-025-22942	I	04/2010 05/01/2012	8580	13580	0
NORTH VACUUM ABO UNIT #129	S	B-23-17S-34E	B	30-025-23100	I	04/2010 05/01/2012	8600	13600	0
NORTH VACUUM ABO UNIT #130	S	H-15-17S-34E	H	30-025-23288	I	04/2010 05/01/2012	12612	17612	0
NORTH VACUUM ABO UNIT #131	S	B-10-17S-34E	B	30-025-23829	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO UNIT #134	S	L-12-17S-34E	L	30-025-23461	O	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #135	S	L-11-17S-34E	L	30-025-23460	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #136	S	D-26-17S-34E	D	30-025-23462	I	04/2010 05/01/2012	9376	14376	0
NORTH VACUUM ABO UNIT #137	S	B-26-17S-34E	B	30-025-23527	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #138	S	L-26-17S-34E	L	30-025-23540	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #140	S	P-11-17S-34E	P	30-025-23560	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #142	S	J-14-17S-34E	J	30-025-23566	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #143	S	B-27-17S-34E	B	30-025-23565	I	04/2010 05/01/2012	8745	13745	0
NORTH VACUUM ABO UNIT #144	S	P-15-17S-34E	P	30-025-23567	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #145	S	P-27-17S-34E	P	30-025-23568	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #146	S	B-14-17S-34E	B	30-025-23646	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #148	S	N-11-17S-34E	N	30-025-23644	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #149	S	J-27-17S-34E	J	30-025-23648	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #150	S	N-12-17S-34E	N	30-025-23645	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #151	S	F-23-17S-34E	F	30-025-23658	I	04/2010 05/01/2012	12180	17180	0
NORTH VACUUM ABO UNIT #152	S	B-13-17S-34E	B	30-025-23693	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #155	S	D-23-17S-34E	D	30-025-23695	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #156	S	J-23-17S-34E	J	30-025-23696	I	04/2010 05/01/2012	9413	14413	0
NORTH VACUUM ABO UNIT #157	S	H-27-17S-34E	H	30-025-23782	I	04/2010 05/01/2012	12500	17500	0
NORTH VACUUM ABO UNIT #158	S	J-12-17S-34E	J	30-025-23713	I	04/2010 05/01/2012	11800	16800	0
NORTH VACUUM ABO UNIT #159	S	P-12-17S-34E	P	30-025-23697	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #160	S	B-12-17S-34E	B	30-025-23698	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #161	S	H-12-17S-34E	H	30-025-23699	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #162	S	J-11-17S-34E	J	30-025-23830	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #163	S	J-15-17S-34E	J	30-025-23820	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO UNIT #164	S	B-15-17S-34E	B	30-025-23821	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO UNIT #165	S	D-13-17S-34E	D	30-025-23753	O	04/2010 05/01/2012	10600	15600	0
NORTH VACUUM ABO UNIT #166	S	H-10-17S-34E	H	30-025-23819	I	04/2010 05/01/2012	8850	13850	0
NORTH VACUUM ABO UNIT #169	S	H-13-17S-34E	H	30-025-23979	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #170	S	D-14-17S-34E	D	30-025-23980	I	03/2000 04/01/2002	8800	13800	Y 13800
NORTH VACUUM ABO UNIT #171	S	N-14-17S-34E	N	30-025-23986	I	04/2010 05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #172	S	P-3-17S-34E	P	30-025-24006	I	04/2010 05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #173	S	F-14-17S-34E	F	30-025-24025	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #175	S	H-14-17S-34E	H	30-025-24325	I	04/2010 05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #200	S	L-2-17S-34E	L	30-025-22031	I	04/2010 05/01/2012	10900	15900	0
NORTH VACUUM ABO UNIT #201	S	J-10-17S-34E	J	30-025-23723	I	04/2010 05/01/2012	12740	17740	0
NORTH VACUUM ABO UNIT #202	S	P-10-17S-34E	P	30-025-23675	I	04/2010 05/01/2012	8900	13900	0
NORTH VACUUM ABO UNIT #203	S	B-22-17S-34E	B	30-025-23647	I	04/2010 05/01/2012	8900	13900	0



NORTH VACUUM ABO UNIT #204	S	D-24-17S-34E	D	30-025-22106	I	04/2010	05/01/2012	10359	15359	0
NORTH VACUUM ABO UNIT #205	S	B-24-17S-34E	B	30-025-22105	I	04/2010	05/01/2012	10401	15401	0
NORTH VACUUM ABO UNIT #206	S	I-19-17S-35E	D	30-025-23794	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #207	S	H-24-17S-34E	H	30-025-22760	I	04/2010	05/01/2012	8653	13653	0
NORTH VACUUM ABO UNIT #208	S	H-22-17S-34E	H	30-025-23981	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #209	S	J-22-17S-34E	J	30-025-23777	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #210	S	L-23-17S-34E	L	30-025-24044	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #211	S	J-24-17S-34E	J	30-025-22712	I	04/2010	05/01/2012	10200	15200	0
NORTH VACUUM ABO UNIT #212	S	P-24-17S-34E	P	30-025-22400	I	04/2010	05/01/2012	10200	15200	0
NORTH VACUUM ABO UNIT #213	S	N-23-17S-34E	N	30-025-23982	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #214	S	D-11-17S-34E	D	30-025-23758	I	04/2010	05/01/2012	8714	13714	0
NORTH VACUUM ABO UNIT #215	S	A-11-17S-34E	A	30-025-21712	O	04/2010	05/01/2012	13370	18370	0
NORTH VACUUM ABO UNIT #216	S	H-11-17S-34E	H	30-025-23720	I	04/2010	05/01/2012	8685	13685	0
NORTH VACUUM ABO UNIT #217	S	F-11-17S-34E	F	30-025-23674	I	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #218	S	F-25-17S-34E	F	30-025-24605	I	04/2010	05/01/2012	8600	13600	0
NORTH VACUUM ABO UNIT #219	S	N-13-17S-34E	N	30-025-24612	I	04/2010	05/01/2012	8650	13650	0
NORTH VACUUM ABO UNIT #220	S	P-22-17S-34E	P	30-025-24748	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #221	S	I-19-17S-35E	E	30-025-24850	O	04/2010	05/01/2012	10127	15127	0
NORTH VACUUM ABO UNIT #222	S	I-24-17S-34E	I	30-025-24851	O	04/2010	05/01/2012	8660	13660	0
NORTH VACUUM ABO UNIT #223	S	A-13-17S-34E	A	30-025-25098	O	04/2010	05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #224	S	B-11-17S-34E	B	30-025-25096	I	04/2010	05/01/2012	8730	13730	0
NORTH VACUUM ABO UNIT #225	S	I-11-17S-34E	I	30-025-25306	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #226	S	K-12-17S-34E	K	30-025-25307	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #227	S	G-12-17S-34E	G	30-025-25308	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #228	S	N-10-17S-34E	N	30-025-23965	I	04/2010	05/01/2012	8925	13925	0
NORTH VACUUM ABO UNIT #229	S	L-10-17S-34E	L	30-025-24090	I	04/2010	05/01/2012	8973	13978	0
NORTH VACUUM ABO UNIT #230	S	J-13-17S-34E	J	30-025-22344	I	04/2010	05/01/2012	10600	15600	0
NORTH VACUUM ABO UNIT #231	S	P-13-17S-34E	P	30-025-23864	I	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #233	S	A-12-17S-34E	A	30-025-28008	O	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #234	S	I-23-17S-34E	I	30-025-28314	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #235	S	K-24-17S-34E	K	30-025-28315	O	04/2010	05/01/2012	8675	13675	0
NORTH VACUUM ABO UNIT #236	S	C-25-17S-34E	C	30-025-28316	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #237	S	A-26-17S-34E	A	30-025-28317	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #238Y	S	M-24-17S-34E	M	30-025-28466	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #239	S	E-25-17S-34E	E	30-025-28585	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #240	S	I-26-17S-34E	I	30-025-28600	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #241	S	K-26-17S-34E	K	30-025-28601	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #242	S	G-26-17S-34E	G	30-025-28602	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #243	S	C-26-17S-34E	C	30-025-28586	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #244	S	O-23-17S-34E	O	30-025-28603	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #245	S	K-23-17S-34E	K	30-025-28604	O	04/2010	05/01/2012	8711	13711	0
NORTH VACUUM ABO UNIT #246	S	O-24-17S-34E	O	30-025-28587	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #247	S	G-24-17S-34E	G	30-025-28627	O	04/2010	05/01/2012	8710	13710	0
NORTH VACUUM ABO UNIT #248	S	E-24-17S-34E	E	30-025-28618	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #249	S	E-26-17S-34E	E	30-025-28722	O	04/2010	05/01/2012	8720	13720	0
NORTH VACUUM ABO UNIT #250	S	A-24-17S-34E	A	30-025-28723	O	04/2010	05/01/2012	9100	14100	0
NORTH VACUUM ABO UNIT #251	S	C-24-17S-34E	C	30-025-28734	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #252	S	M-13-17S-34E	M	30-025-28735	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #253	S	O-13-17S-34E	O	30-025-28736	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #254	S	I-13-17S-34E	I	30-025-28724	O	04/2010	05/01/2012	9100	14100	0
NORTH VACUUM ABO UNIT #255	S	K-13-17S-34E	K	30-025-28737	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #256	S	I-14-17S-34E	I	30-025-28738	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #257	S	E-13-17S-34E	E	30-025-28739	O	04/2010	05/01/2012	9100	14100	0
NORTH VACUUM ABO UNIT #258	S	G-13-17S-34E	G	30-025-28740	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #259	S	A-14-17S-34E	A	30-025-28830	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #260	S	C-13-17S-34E	C	30-025-28821	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #261	S	O-12-17S-34E	O	30-025-28855	O	04/2010	05/01/2012	8708	13708	0
NORTH VACUUM ABO UNIT #262	S	M-12-17S-34E	M	30-025-28903	O	04/2010	05/01/2012	8750	13750	0
NORTH VACUUM ABO UNIT #263	S	O-11-17S-34E	O	30-025-28822	O	04/2010	05/01/2012	8699	13699	0
NORTH VACUUM ABO UNIT #264	S	M-11-17S-34E	M	30-025-28831	O	04/2010	05/01/2012	8600	13800	0
NORTH VACUUM ABO UNIT #265	S	K-11-17S-34E	K	30-025-28832	O	04/2010	05/01/2012	8700	13700	0
NORTH VACUUM ABO UNIT #266	S	G-11-17S-34E	G	30-025-28904	O	04/2010	05/01/2012	8807	13807	0
NORTH VACUUM ABO UNIT #267	S	E-11-17S-34E	E	30-025-28833	O	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #268	S	I-10-17S-34E	I	30-025-28834	O	04/2010	05/01/2012	8791	13791	0
NORTH VACUUM ABO UNIT #269	S	A-15-17S-34E	A	30-025-28919	O	04/2010	05/01/2012	8830	13830	0
NORTH VACUUM ABO UNIT #270	S	O-10-17S-34E	O	30-025-28936	O	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #271	S	G-10-17S-34E	G	30-025-28938	O	04/2010	05/01/2012	8800	13800	0
NORTH VACUUM ABO UNIT #272	S	A-10-17S-34E	A	30-025-28939	O	04/2010	05/01/2012	8850	13850	0
NORTH VACUUM ABO UNIT #273	S	C-11-17S-34E	C	30-025-28940	O	04/2010	05/01/2012	8800	13800	0

INFORMATION SHEET FOR PART 5.9

Oil Conservation Division (OCD) Rule 19.15.5.9 NMAC, commonly known as “Part 5.9,” requires operators to meet certain minimum compliance standards for the wells they already operate before they can drill, acquire, produce or inject into additional wells. If an operator is out of compliance as defined by Part 5.9, the OCD:

- May deny registration by the operator or certain related entities. See 19.15.9.8(B) NMAC.
- May deny applications for change of operator that would transfer wells to the operator. See 19.15.9.9(C) NMAC.
- Must deny injection permits. See 19.15.26.8(A) NMAC.
- May deny APDs. See 19.15.14.10(A) NMAC.
- Must deny allowable and authorizations to transport. See 19.15.16.19(A) NMAC.

In addition, the OCD may, after notice and hearing, revoke previously issued injection permits if the operator is out of compliance with Part 5.9. See 19.15.26.8(A) NMAC.

To stay in compliance with Part 5.9, an operator must:

- Keep current with the financial assurance requirements for well plugging. See 19.15.5.9(A)(1) NMAC.
- Comply with orders requiring corrective action. See 19.15.5.9(A)(2) NMAC.
- Pay properly assessed penalties. See 19.15.5.9(A)(3) NMAC.
- Have no more than a certain number of wells out of compliance with the inactive well rule. See 19.15.5.9(A)(4) NMAC.

FINANCIAL ASSURANCE REQUIREMENTS: The OCD’s financial assurance requirements for well plugging are set out in 19.15.8.9 NMAC. The OCD requires all state or fee wells to be covered by a financial assurance. The OCD does not require financial assurances for Federal or Indian wells.

The operator must either post a blanket financial assurance in the amount of \$50,000 to cover its state or fee wells, or post single-well financial assurances for each state or fee well in the amount set by the rule.

If the operator chooses to post a blanket financial assurance, it must also post single-well financial assurances for each state or fee well that has been inactive for more than two years that has not been plugged and released. Note that a single-well financial assurance is required even if the well is on approved temporary abandonment status, and even if the wellbore of the well has been plugged. To check compliance with this requirement, go to www.emnrd.state.nm.us/OCD, OCD Online, E-Permitting, Financial Assurance. Insert the operator name or OGRID, and hit “Get Report.” The report will list all the wells for that operator that have not been plugged and released. Wells currently in violation of the single-well financial assurance requirement will have a “Y” in the far right column, titled “In Violation.”

For information on how to post financial assurances, please contact OCD Financial Assurance Administrator Dorothy Phillips, (505) 476-3461, Dorothy.phillips@state.nm.us.

CORRECTIVE ACTION REQUIREMENTS: If an operator fails to take an action required by a hearing order or an agreed compliance order, the OCD may go to hearing to obtain a formal order finding the operator “in violation of an order requiring corrective action.” Once such an order is issued and becomes final, the

operator will be out of compliance with Part 5.9 until that order is lifted. To lift the order, the operator must complete the corrective action required, and file a motion to declare the order satisfied. The Oil Conservation Division or the Oil Conservation Commission, as appropriate, may grant the motion without hearing or may set the matter for hearing.

UNPAID PENALTIES: An operator with a penalty assessment unpaid more than 70 days after issuance of the order assessing the penalty will be in violation of Part 5.9 until that penalty is paid. Penalties may be assessed by the district court, or may be agreed to by the operator under an agreed compliance order entered into to resolve a compliance action.

INACTIVE WELLS: The inactive well rule, 19.15.25.8 NMAC, requires any well that has been inactive for a period of more than 15 months to be plugged and abandoned, placed on approved temporary abandonment status, or returned to production or other beneficial use. An operator will be out of compliance with Part 5.9 if it has too many wells in violation of the inactive well rule; the number of non-compliant wells allowed depends on the size of the operator. Under Part 5.9, if an operator operates:

- 1 well, it may have no wells out of compliance;
- 2 or 3 wells, it may have no more than 1 well out of compliance;
- 4 to 100 wells, it may have no more than 2 wells out of compliance;
- 101 to 500 wells, it may have no more than 5 wells out of compliance;
- 501 to 1000 wells, it may have no more than 7 wells out of compliance; and
- 1000 or more wells, it may have no more than 10 wells out of compliance.

To check compliance with 5.9 as to inactive wells, go to www.emnrd.state.nm.us/OCD, OCD Online, E-Permitting, Inactive Well List. Do not change the default search terms. Insert the operator name or OGRID, and hit "Get Report." The report will identify the wells that -- according to OCD records -- have been inactive for 15 months, are not on approved temporary abandonment status, do not have a plugged wellbore, and are not subject to an inactive well agreed compliance order. For purposes of Part 5.9, if a well appears on this list, there is a rebuttable presumption that the well is in violation of the inactive well rule. The heading of the list will also identify the total well count for the operator, and the total number of non-compliant inactive wells, so you can determine if the operator is in compliance with Part 5.9.

If your company has more non-compliant wells than allowed under Part 5.9, you will need to return wells to compliance by returning them to production or other beneficial use, placing them on approved temporary abandonment status, or plugging the wellbore. In some limited circumstances, the OCD may be willing to enter into an inactive well agreed compliance order setting a schedule for returning the wells to compliance and imposing sanctions if that schedule is not met. Wells covered by an inactive well agreed compliance order are not included when calculating Part 5.9 compliance. For information on inactive well agreed compliance orders, contact OCD Attorney Sonny Swazo at (505) 476-3463, Sonny.swazo@state.nm.us.