



# NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON**

Governor

**Joanna Prukop**  
Cabinet Secretary

**Lori Wrotenbery**

Director

**Oil Conservation Division**

February 10, 2004

Ms. Kay S Eckstein  
Patina San Juan, Inc  
5802 Hwy 64  
Farmington NM 87401

Re: Northwest 4E, I-08-26N-04W, API 30-39-23578

Dear Ms. Eckstein:

The 2003 Packer Leakage Test on the referenced well indicates communication between the producible zones. In order to comply with Rule #112A, you are hereby directed to initiate remedial activity and retest the well to show separation of the zones prior to April 1, 2004.

Place this reference # on all future correspondence CTP0404054806

If you have any questions, please call me at 505-334-6178, ext. 16.

Sincerely yours,

Charlie T. Perrin  
Deputy Oil & Gas Inspector  
cperrin@state.nm.us

CTP/mk

CC: CTP  
Well File