



Schematic - Current

SAN JUAN 30-6 UNIT #35B

API-30-039-30871

District NORTH	Field Name MV/DK COM	API / UWI 3003930871	County RIO ARRIBA	State/Province NEW MEXICO	
Original Spud Date 8/9/2010	Surface Legal Location 024-030N-006W-J	East/West Distance (ft) 765.00	East/West Reference FEL	North/South Distance (ft) 2,280.00	North/South Reference FSL

Well Config: DEVIATED - Original Hole, 10/27/2010 2:48:40 PM

ftKB (MD)

Schematic - Actual

16		2-1, Casing Hanger, 7, 6.366, 16, 1.0
17		3-1, Casing Hanger, 4 1/2, 4.000, 16, 1.0
19		1-1, CASING HANGER, 9 5/8, 9.001, 16, 3.3
35		2-2, Casing Pup Joint, 7, 6.366, 17, 18.0
232		1-2, CASING JOINTS, 9 5/8, 9.001, 19, 212.2
232		1-3, SAW TOOTH COLLAR, 9 5/8, 9.001, 232, 0.8
237		
2,920		2-3, Casing Joints, 7, 6.366, 35, 2,885.3
2,923		2-4, Stage Collar, 7, 6.366, 2,920, 3.0
4,116		1-1, Tubing, 2 3/8, 1.995, 16, 7,824.9
4,126		3-2, Casing Joints, 4 1/2, 4.000, 17, 4,098.7
4,182		3-3, Marker Joint, 4 1/2, 4.000, 4,116, 10.1
4,183		2-5, Casing Joints, 7, 6.366, 2,923, 1,258.7
4,225		2-6, Float Collar, 7, 6.366, 4,182, 1.0
4,226		2-7, Casing Joints, 7, 6.366, 4,183, 42.1
4,236		2-8, Float Shoe, 7, 6.366, 4,225, 1.0
4,546		
5,017		Perforated, 4,546-5,017, 9/29/2010
5,102		
5,558		Perforated, 5,102-5,558, 9/29/2010
5,646		
6,026		Perforated, 5,646-6,026, 9/29/2010
7,563		3-4, Casing Joints, 4 1/2, 4.000, 4,126, 3,436.9
7,573		3-5, Marker Joint, 4 1/2, 4.000, 7,563, 10.0
7,826		
7,828		
7,841		1-2, Tubing Pup Joint, 2 3/8, 1.995, 7,841, 1.9
7,843		1-3, Tubing, 2 3/8, 1.995, 7,843, 30.5
7,873		1-4, Profile Nipple, 2 3/8, 1.780, 7,873, 0.8
7,874		1-5, Expendable Check w/ Mule Shoe, 2 3/8, 7,874, 0.9
7,875		Perforated, 7,828-7,932, 9/28/2010
7,932		
7,946		
7,971		3-6, Casing Joints, 4 1/2, 4.000, 7,573, 398.0
7,971		3-7, Float Collar, 4 1/2, 4.000, 7,971, 0.6
7,972		3-8, Float Shoe, 4 1/2, 4.000, 7,971, 0.6
7,973		

