RECEIVED

Form 3160-5 UNITED STATES JAN 20 **20**11 kcub JAN 25:11 FORM APPROVED (February 2005) DEPARTMENT OF THE INTERIOR OMB No. 1004-0137 Expires: March 31, 2007 BUREAU OF LAND MANAGEMENT armington Field Office Bureau of Land Managem 2151 Lease Serial No. SF-078763 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. Rosa Unit 1. Type of Well 8. Well Name and No. Rosa Unit #41A Oil Well Gas Well Other 2. Name of Operator 9. API Well No. Williams Production Company, LLC 30-039-25506 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-634-4208 Blanco Mesaverde 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State 2180' FSL & 1485' FEL, sec 5, T31N, R5W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Production (Start/Resume) Acidize Deepen Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Other Clean Out/ Subsequent Report Return to production Change Plans Plug and Abandon Temporarily Abandon Convert to Final Abandonment Notice Plug Back Water Disposal Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Williams Production intends to clean out and return this well to production as follows: 1. MIRU, kill, ND tree, & NU BOP's. 2. POOH with tubing. 3. Clean out fill to PBTD. 4. ND BOP's & NU tree. 5. Release rig. 6. Return to production. by 4/1/11 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Larry Higgins Title Permit Supervisor Signature Date 1-20-11 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by JAN 2 1 2011 Original Signed: Stephen Mason Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.





Office



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington Field Office 1235 La Plata Highway, suite A Farmington, New Mexico 87401

IN REPLY REFER TO:

NMSF-078763 (WC) 3162.3-2 (21110)

Ms. Rachel Lipperd Williams Production Co. PO Box 3102 MS 25-4 Tulsa, OK 74101

Dear Ms. Lipperd:



January 13, 2011

Our records indicate that you are the operator of the following well:

1) No. 41A Rosa Unit, 2180' FSL & 1485' FEL sec. 5, T. 31 N., R. 5 W., Rio Arriba County, New Mexico, Lease NMSF-078763. Well has not produced since September, 2009.

Title 43 CFR Section 3162.3-4 requires that the lessee shall promptly plug and abandon, condition as a service well, or condition as a water well, any well on a lease that is not used or useful for the purpose of the lease. Accordingly, you are required to advise this office by Sundry Notice within 30 calendar days of your intent to perform one of the following: a) Condition the well to a useful function, b) Temporarily abandon the well, c) Continued shut-in status, d) Permanently plug and abandon the well.

See attached General Requirements for Non-Producing wells on Federal leases.

The 30 calendar days commences upon receipt of this letter or seven days from the date it is mailed, whichever is less. Failure to comply within the 30 calendar days may result in an assessment in accordance with 43 CFR 3163.1.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P. O. Box 27115, Santa Fe, New Mexico 87502-0115. Such request shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 *et seq*.

If you have any questions, please contact Stephen Mason with this office at (505) 599-6364.

Sincerely,

Stephen Mason

Petroleum Engineer, Petroleum Management Team

1 Attachment