UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



FFR 28 2011

| | Cundry Motions and Day | | | | |
|--|--|--|--|--------------------------|---------------------------------------|
| | Sundry Notices and Rep | ports on Wells | | amirgton! | |
| | | | | au of l _s and | |
| . " | Type of Well | | 9931-123456) | 6. | NM-04226 If Indian, All. or |
| | GAS | | (A) A | | Tribe Name |
| | | | RECEIVED | 3 7. | Tinit American and Norma |
| . I | Name of Operator | | % MAR 2011 | 2.3 | Unit Agreement Name |
| | BURLINGTON | | OIL CONS. DIV. DIST. 3 | <i>13</i> / | |
| - | RESCURCES OIL | L & GAS COMPANY LP | \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ | 8. | |
| . / | Address & Dhone No. of One | a wataw | 65/20201 01 F/3/ | 8. | Well Name & Number |
| . / | Address & Phone No. of Ope | erator | RECEIVED MAR 2011 OIL CONS. DIV. DIST. 3 CELEOZGUSLIV. | | McManus 13R |
| | PO Box 4289, Farmington, N | M 87499 (505) 326-9700 | | 9. | API Well No. |
| | | | ************************************** | | 30-045-32604 |
| . 1 | Location of Well, Footage, S | ec., T, R, M | | | |
| | Unit K (NESW), 1810' FSL a | & 1445' FWI. Section 4 TO | 25N RRW NMPM | 10. | Field and Pool Ballard Pictured Cliff |
| • | om a trestry, total roll (| 1770 E 11 12, DUUHUH 4, 12 | iotry ito try triffit (ti | , , | |
| | | | | 11. | County and State San Juan, NM |
| | | | | · | |
| | CHECK APPROPRIATE BO | | RE OF NOTICE, REPORT, | OTHER | DATA |
| '! | Type of Submission Ty Notice of Intent | pe of Action Abandonment | Change of Plans | Х | Other – Pump Install |
| | | Recompletion | New Construction | | Tump motan |
| | X Subsequent Report | Plugging | Non-Routine Fracturin | g | |
| | Subsequent Report | | 177 . 00 . 00 | | |
| | Final Abandonment | Casing Repair Altering Casing | Water Shut off Conversion to Injection | 1 | |
| | | Casing Repair Altering Casing | Water Shut off Conversion to Injection | 1 | ,a., |
| | | Altering Casing | 744 | 1 | |
| 2/09 | Final Abandonment Describe Proposed or Compl 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224' | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PO | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224 111/ | Final Abandonment Describe Proposed or Compl 0/2011 MIRU KEY 15. ND W 1 (New set depth) w/ F-Nipple 1 1. | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pg | Conversion to Injection OOH w/ tbg. Circ clean. RIH | w/ 70jts, 2 | |
| 2/09 224 /11/ | Final Abandonment Describe Proposed or Comple 0/2011 MIRU KEY 15. ND W | Altering Casing letted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pg going is true and correct. | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods | w/ 70jts, 2 . NU WH. | RD RR @ 15:00hrs on |
| 2/09 224 11/ | Final Abandonment Describe Proposed or Compl 0/2011 MIRU KEY 15. ND W 1 (New set depth) w/ F-Nipple 1 1. | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pg | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods | w/ 70jts, 2 . NU WH. | RD RR @ 15:00hrs on |
| 2/09 224 111/ | Final Abandonment Describe Proposed or Compl 0/2011 MIRU KEY 15. ND W 1 (New set depth) w/ F-Nipple 1 1. | Altering Casing letted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pg going is true and correct. | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods | w/ 70jts, 2 . NU WH. | RD RR @ 15:00hrs on |
| 2/09 2224 111/ 4. I | Pinal Abandonment Describe Proposed or Comple O/2011 MIRU KEY 15. ND W O/2011 MIRU KEY 15. ND | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pg going is true and correct. Crystal Ta | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods | w/ 70jts, 2 . NU WH. | RD RR @ 15:00hrs on |
| 2/09 224 11/ 11/ gne This | Pinal Abandonment Describe Proposed or Comple 2/2011 MIRU KEY 15. ND W (New set depth) w/ F-Nipple 11. hereby certify that the forest space for Federal or State Off ROVED BY | going is true and correct. Crystal Talescone Altering Casing Title | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods | w/ 70jts, 2 . NU WH. | chnician Date 2/28/ |
| 2/09 224 111/ 111/ gne This PPF ON | Final Abandonment Describe Proposed or Complete Proposed Propo | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pr going is true and correct. Crystal Table fice use) Title any: son knowingly and willfully to make any departs | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods afoya Title: Staff Reg | w/ 70jts, 2 . NU WH. | chnician Date 2/28/ |
| 2/09 224 111/ 111/ Igne This PPF ON | Pinal Abandonment Describe Proposed or Comple 2/2011 MIRU KEY 15. ND W (New set depth) w/ F-Nipple 11. hereby certify that the forest space for Federal or State Off ROVED BY DITION OF APPROVAL, if a | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pr going is true and correct. Crystal Table fice use) Title any: son knowingly and willfully to make any departs | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods afoya Title: Staff Reg | w/ 70jts, 2 . NU WH. | chnician Date 2/28/ Date |
| 2/09/224 //11/ 4. I digne This APPF | Final Abandonment Describe Proposed or Complete Proposed Propo | Altering Casing leted Operations VH. NU BOPE. PT BOPE. PG @ 2190'. ND BOPE. Run Pr going is true and correct. Crystal Table fice use) Title any: son knowingly and willfully to make any departs | Conversion to Injection OOH w/ tbg. Circ clean. RIH ump & Rods. Space out rods afoya Title: Staff Reg | w/ 70jts, 2 . NU WH. | chnician Date 2/28/ |