


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised June 10, 2003



Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|-----------------------------------|---------------|------------------------|
| Name of Company | Burlington Resources | Contact | Gregg Wurtz |
| Address | P.O. Box 4289 Farmington NM 87499 | Telephone No. | (505) 326-9537 |
| Facility Name | SAN JUAN 30-6 UNIT | 477 | Facility Type Gas Well |
| Surface Owner | Fed | Mineral Owner | Fed |
| Lease No. | FEE | | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|----------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| M | 28 | 030N | 006W | 1230 | South | 790 | West | San Juan |

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|----------------------|----------------------------|----------------------|
| Type of Release | Produced water | Volume of Release | 10 BBLs. | Volume Recovered | 0 BBLs. |
| Source of Release | Production water storage tank | Date and Hour of Occurrence | 12/1/2005 7:00:00 AM | Date and Hour of Discovery | 12/1/2005 7:00:00 AM |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | | | |
| By Whom? | Date and Hour | | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. 0 | | | |

If a Watercourse was Impacted, Describe Fully.*

None

Describe Cause of Problem and Remedial Action Taken.*

Leak in the water storage tank. Standing water discovered inside the containment berm. No visible corrosion or failures were observed on tank. A dye was added to tank water to identify potential leak. The leak was discovered and the tank was removed from service and replaced.

Describe Area Affected and Cleanup Action Taken.*

Area within the tank containment. No remedial actions taken.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---|--------------------------------------|
| Signature: <i>Gregg Wurtz</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Gregg Wurtz | Approved by District Supervisor: <i>Denny Hart</i> for Charlie Perrin | |
| Title: Environmental Representative | Approval Date: 12/22/05 | Expiration Date: |
| E-mail Address: lhasely@br-inc. com or gwurtz@br-inc.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 12/5/05 Phone: (505) 326-9841 or 9537 | | |

* Attach Additional Sheets If Necessary

n DGF0535636476