District 1 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources DEC 2004

Santa Fe, NM 87505

PASCE/VSD Oil Conservation Division OIL COMO. DIV. 1220 South St. Francis Dr.

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action									
					PERATOR	,	Finitial Repo	ort 🛛 Final Report	
		onocoPhi			Contact	Monica	nica D. Olson		
Address Facility Nar				ton, NM 8740	Telephone No Facility Type		505-599-3458 Producing Gas Well API # 30-039-21055		
Facility Name San Juan 29-5 Unit #77 Surface Owner Federal Mineral Owner							Lease No	API # 30-039-21055 SF-078917	
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County								County	
L	26	T29N	RŚW	1450'		1100'			
Latitude 36.69323° Longitude 107.3321°									
Type of Release – Produced Water Volume of Release – 50 BBL Volume Recovered - 50 BBL									
				er truck failed	Date and Hour		our of Discovery		
to pull at s			OW WALL	er truck falled	12/11/04				
Was Immediate Notice Given? If YES, To Whom?									
			Yes ∐ No	☐ Not Require		Denny Foust – OCD – via email			
By Whom?		Monica	Olson			Mark Kelly – BLM – via email Date and Hour – 12/13/04 – 12:00 p.m. via e-mail			
Was a Water	course Reac					Impacting the W			
Yes No									
If a Watercourse was Impacted, Describe Fully.*									
Describe Cause of Problem and Remedial Action Taken.* A produced water spill of 40 BBL was discovered on Saturday morning, 12/11/04 by the lease operator. The well had just been turned on after a recompletion on Friday, 12/10/04 at 10:00 a.m. and was making a lot of water. A contract water truck failed to pull a load from the 45 BBL pit tank on Friday, and it overflowed 40 BBL into the bermed area. All 40 BBL was recovered. The water hauling company was contacted to ensure they would check the well daily and pull the water, so the well was kept on and flowing. Another 10 BBL spill from this same pit tank was then discovered on Monday morning, 12/13/04 by the lease operator. Apparently, the water hauler went to this location late Saturday/early Sunday, but looked at the wrong pit tank for pulling. All of the water was contained within the bermed area, and 10 BBL was recovered with a vacuum truck. The well is now shut in until a larger tank can be installed on location.									
Describe Area Affected and Cleanup Action Taken.* No water left the berm. All spilled fluids were recovered (50 BBL). The well has been shut in until a larger tank can be installed on location. This will be the final report.									
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.									
	NA~	\a.`a (\bigcirc \bigcirc	• •		OIL CONSERVATION DIVISION			
Signature:		ville '	W. UU	YOY 1		Approved by District Supervisor: for Charle Perrin			
Printed Name	: M	onica D. O	Ison		Approved by D	Approved by District Supervisor: for Charle Perrin			
Title: Safety, Health, Environmental, & Regulatory Technician Approval Date: 12/27/04 Expiration Date:								nte:	
E-mail Addre	ss: monic	a.olson@d	conocoph	illips.com	Conditions of A	pproval:		Attached	
Date: 1	2/13/04		Phone:	505-599-3458					
Attach Additional Sheets If Necessary									

n DGF 0436235612