Form 3160-5 FORM APPROVED **UNITED STATES** (August 1999) OMB NO. 1004-0135 DEPARTMENT OF THE INTERIOR Expires: November 30, 2000 **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter any abandoned well. Use form 3160-3 (APD) for suefoproposals. NMSF079596 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on reverse side 7. If Unit or CA/Agreement, Name and/or No. NMNM73894 1. Type of Well Well Name and No. OU CONS. DIV. MARTIN GASCOM F 1R 🗖 Oil Well 🛛 Gas Well 🔲 Other HOLLY PERKINS 3 E-Mait Holly Perkins@xtoenergy 2. Name of Operator XTO ENERGY INC 9. API Well No. Contact: 30-045-25625-00-S1 3b. Phone No. (include area code Ph: 503-324,1090 Ext. 402 Fx: 505.564-6799 3a. Address 10. Field and Pool, or Exploratory 2700 FARMINGTON AVE., BLDG K, SUITE 1 **BASIN DAKOTA** FARMINGTON, NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 14 T27N R10W SENW 1850FNL 1520FWL SAN JUAN COUNTY, NM 36.57718 N Lat, 107.86812 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize Deepen □ Production (Start/Resume) ■ Water Shut-Off Notice of Intent ☐ Fracture Treat ☐ Alter Casing □ Reclamation ■ Well Integrity ☐ Subsequent Report ■ New Construction □ Recomplete Other ☐ Final Abandonment Notice □ Change Plans □ Plug and Abandon ☐ Temporarily Abandon □ Convert to Injection □ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filled once. following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 10/21/02: XTO Energy moved on location & found 2 casing leaks @ 3,846' & 383'. SWI over weekend. Received verbal authority to repair leak from Jim Lovato, per the following measures: Set CIBP @ 3,875' Set cmt retainer @ 3,700' & spot 20 sx of micro mx cmt. Press to 500 psig. Set CBP @ 400'. Acidize csg leak @ 383' & circ to surf. Pmp cmt slurry to surf. SD WOC. 6. DO CBP & tst to 500 psig. RWTP.

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #16017 verified For XTO ENERGY INC, Committed to AFMSS for processing by Ma	sent to	the Farmington	Ε)
Name (Printed/Typed)	DARRIN STEED	Title	OPERATIONS ENGINEER	•
Signature	(Electronic Submission)	Date	11/18/2002	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	
_Approved By_JIM_LQVATO		TitleF	PETROLEUM ENGINEER	Date 12/09/2002
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	: Farmington	
Title 18 U.S.C. Section 100	1 and Title 43 U.S.C. Section 1212, make it a crime for any po	rson kno	wingly and willfully to make to any dep	artment or agency of the United