

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Santa Fe Pacific R R
9. Well No. 8
10. Field and Pool, or Wildcat Chaco Wash Mesaverde
12. County McKinley

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)


1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole
2. Name of Operator Henry S. Birdseye
3. Address of Operator P. O. Box 8294, Albuquerque, N. M. 87108
4. Location of Well UNIT LETTER <u>C</u> , <u>330</u> FEET FROM THE <u>north</u> LINE AND <u>1650</u> FEET FROM THE <u>west</u> LINE, SECTION <u>27</u> TOWNSHIP <u>20 N</u> RANGE <u>9 W</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 6450 est. Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was spudded 11-1-68. Hole is 10" diameter.  
Well was drilled with cable tools by Kenneth McDonald to T.D. 520'. There were no shows of oil or gas and no water sands to total depth. Reached T.D. 1-3-69.  
Plan to plug well with 35 sacks common cement at 450-520', 25 sacks from 330-380' (producing zone at Chaco Wash), and from surface to 20' with 10 sacks. Will install steel marker. Heavy mud to be left between plugs.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>MB Birdseye</u>	TITLE <u>Operator</u>	DATE <u>2-24-69</u>
APPROVED BY <u>W. R. Kendrick</u>	TITLE <u>SUPERVISOR</u>	DATE <u>JUN 2 1971</u>
CONDITIONS OF APPROVAL, IF ANY:		

PETROLEUM ENGINEER DIST. NO. 5