

DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

(Other side of this form is reverse side)

USA-NM-8270

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SURVEY	
2. NAME OF OPERATOR Tenneco Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Suite 1200 Lincoln Tower Building, Denver, Colo. 80203		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  2265' F/SL and 330' F/EL		8. FARM OR LEASE NAME Hotchkiss-Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6937 GR		10. FIELD AND POOL, OR WILDCAT Undesignated Dakota	
		11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA Sec. 2, T-17-N, R-9-W	
		12. COUNTY OR PARISH McKinley	13. STATE New Mexico


16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	(Other) <input type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Well was T.A. on 1-14-70. We propose to P & A well as follows:  
2848' to 2500' cement inside casing across the Dakota. If casing is cut at 1900' cement plug to be installed 1900' to 1950' and if casing is not cut, 50' of cement inside casing from 1850' - 1900'. Install 100 ft. of cement across Hospah from 1550' to 1650' in open hole or left in casing.  
Install 10 sacks cement at surface and install dry hole marker 5' above ground level and clean location.



18. I hereby certify that the foregoing is true and correct

SIGNED G. A. Ford TITLE Sr. Production Clerk DATE 4-15-70

(This space for Federal or State office use)

APPROVED BY MP TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side