

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-2779
7. Unit Agreement Name
8. Farm or Lease Name STATE
9. Well No. 22
10. Field and Pool, or Wildcat CHACO WASH MV
12. County N/E/KINLEY

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator BEO ENGINEERING INC
3. Address of Operator PO BOX 2966 SANTA FE, NM 87504-2966
4. Location of Well UNIT LETTER B 990 FEET FROM THE N LINE AND 26.35 FEET FROM THE E LINE, SECTION 28 TOWNSHIP 20N RANGE 9W NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input checked="" type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CONDITIONS OF APPROVAL:

1. Set bridge plug no more than 50' above perforations (489'-499', 308'-315').
2. Load hole with inert fluid.
3. Pressure test casing and bridge plug to 100 psi for 15 minutes.
4. Cap well. Clean location. Install well sign.
5. Notify the Aztec NMOC district office 48 hours in advance of commencement of work.
6. Work must commence by July 22, 1986.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED M. Saw TITLE PETROLEUM ENGINEER DATE 4-15-86

APPROVED BY Carolyn J. [Signature] TITLE Field Representative DATE 5-22-86

CONDITIONS OF APPROVAL, IF ANY: See above.