

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR James L. Lduwick		8. FARM OR LEASE NAME Ludwick
3. ADDRESS OF OPERATOR P.O. Box 70, Farmington, NM 87499		9. WELL NO. #1
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL, 360' FEL		10. FIELD AND POOL, OR WILDCAT Peters Wash Indefinite Mesaverde
14. PERMIT NO.		11. SEC., T., R., M., OR S.W. 1/4 AND SURVEY OR AREA Sec. 7, T19N, R5W
15. ELEVATIONS (Show whether SF, ST, GR, etc.) 6608 GR.		12. COUNTY OR PARISH McKinley
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>	WATER SHUT-OFF	<input type="checkbox"/>
FRACURE TEST	<input type="checkbox"/>	FRACURE TREATMENT	<input type="checkbox"/>
SHOOT OR ACIDISE	<input type="checkbox"/>	SHOOTING OR ACIDISING	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	(Other)	<input type="checkbox"/>
(Other)	<input type="checkbox"/>		
PULL OR ALTER CASING	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
MULTIPLE COMPLETION	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>		

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and components pertinent to this work.)

REQUEST TO PLUG & ABANDON

Plans for plugging well Ludwick #1

1. Tie on to 4 1/2" casing, load hole with water, break down perf's.
2. Perfs at 1844-1846-1850-1897-1906-1933-1943-1944-1955-1956-1957
3. Pump 110 sks. neat cement, 6% gel, yield 1.73, squeeze 5 sks. cement into perfs.
4. Install dry hole marker, back fill pits and reseed location.
5. Work to be completed on or before June 31, 1994.

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

18. I hereby certify that the foregoing is true and correct

SIGNED

James L. Lduwick

TITLE Operator

DATE 10/21/93

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

NOV 4 1993

DISTRICT MANAGER

*See Instructions on Reverse Side

NMOCD

IN REPLY REFER TO:
(07337)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE

1235 La Plata Highway
Farmington, New Mexico 87401

Attachment to Notice of

Re: Permanent Abandonment

Intention to Abandon

Well: 1 Ludwick

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Leases."

2. **Mike Flaniken** with the Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 599-8907.

3. The following modifications to your plugging program are to be made (when applicable):

*After cement has set, Tag top of cement
and refill casing, if Necessary.*

Office Hours: 7:45 a.m. to 4:30 p.m.