Distribution: O+4 (BLM); 1-Accounting; 1-	Crystal; 1-File	
Form 3160-5 UNITED STATES (June 1990) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No. NM-24964 6. If Indian, Allottee or Tribe Name 7. If Unit or CA, Agreement Designation
SUBMIT IN TRIPLICATE		7. If Onit of CA, Agreement Designation
1. Type of Well Oil Gas X Well Well Other 2. Name of Operator Merrion Oil & Gas Corporation 3. Address and Telephone No. 610 Reilly Avenue, Farmington, NM 87401 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		8. Well Name and No. Pot Mesa #4 9. API Well No. 30-031-20890 10. Field and Pool, or Exploratory Area Pot Mesa Mesaverde
465' fnl & 1780' fwl (ne nw)		11. County or Parish, State
C. Section 3, T20N, R6W		McKinley County,
12. CHECK APPROPRIATE BOX (s) TO INDICATE NATURE OF NOTICE, REPO	New Mexico
TYPE OF SUBMISSION	TYPE OF ACTION	II, OR OTHER DATA
X Notice of Intent	Abandonment	X Change of Plans
Subsequent Report	Recompletion Plugging Back Casing Repair	New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection
Final Abandonment Notice	Altering Casing Other	Dispose Water (Note: Report results of multiple completion on Completion or Recompletion Report and Log form.)
13. Describe Proposed or completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) Merrion Oil & Gas proposes to return the subject well to production by May 1, 1997. Economic feasibility of compression and compressor design for the subject well were dependent upon the added production from the McCollum #1, which we expected to recomplete in a lower portion of the Mesaverde. The newly opened zone in the McCollum #1 proved to be nonproductive. Facility redesign without the McCollum production is ongoing, however the weather may cause difficulty in installation of surface equipment. We therefore request additional time to return the well to production.		
14. I hereby certify that the foregoing is true and correct Signed Connie S. Dinning (This space for Federal of Stapooffice use). Spencer	Title Contract Engineer	Date 2/5/97
Approved By Conditions of approval, if any:	Title	Date FEB - 7 1997