

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRI. ATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> 89H	5. LEASE DESIGNATION AND SERIAL NO. USA NM 67402
2. NAME OF OPERATOR Lone Mountain Production Company	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 3394, 408 Petroleum Bldg., Billings, MT 59103	7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1700' FSL, 2000' FEL, Section 6	8. FARM OR LEASE NAME Federal
14. PERMIT NO. 30-031-70001	9. WELL NO. No. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6780' GL, 6788' KB	10. FIELD AND POOL, OR WILDCAT Wildcat
	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA NW 1/4 SE 1/4 Sec. 6: T16N-R7W
	12. COUNTY OR PARISH McKinley
	13. STATE New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugged and abandoned well as follows:

Plug #1: 43 sacks, 2624' - 2724'.
Plug #2: 43 sacks, 1622' - 1722'.
Plug #3: 50 sacks, 175' - surface.

Set dry hole marker. Finished plugging at 5:00 PM on May 1, 1989.

Location will be rehabilitated when mud pits are dry. Seeding will be done in the fall.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

James G. Routson

TITLE Petroleum Engineer

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

FARMINGTON COPY

*See Instructions on Reverse Side

APPROVED

DATE May 2, 1989

MAY 23 1989

AREA MANAGER
FARMINGTON RESOURCE AREA