

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well OIL	API # (assigned by OCD) 30-031-60029
	5. Lease Number Fee
	6. State Oil & Gas Lease #
2. Name of Operator Geo Engineering	7. Lease Name/Unit Name Santa Fe Pacific
	8. Well No. #4
3. Address & Phone No. of Operator P. O. Box 2966 Santa Fe, NM 87505	9. Pool Name or Wildcat
4. Location of Well, Footage, Sec., T, R, M Sec. 20 T-20-N, R-9-W, NMPM, McKinley County Unit O, 320' FSL & 1920' FEL	10. Elevation:

Type of Submission

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

Type of Action

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other -

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

13. Describe Proposed or Completed Operations

A-Plus Well Service, contractor, plugged and abandoned said well according to the attached Daily Report.

This work was completed under State of New Mexico Contract No. 98-521.25-059

SIGNATURE William F. Clark Contractor

March 4, 1998

(This space for State Use)

Approved by Johnny Robinson Title _____

Date _____

A - PLUS WELL SERVICE

P.O. BOX 1979 • FARMINGTON, NM 87499
505-325-2627 • FAX (505) 325-1211

Rig No 6-7

Date 2/6/98

Well No Sanita Fe Pacific #4 Location Sec 20 - 20N R9W Company Geo Engineering

FROM	TO	DESCRIPTION OF OPERATION
2/6/98		
1pm	1:30pm	Rig up WL Run in Hole to 364' in 2" Tubing 4½ csg.
2/24/98		
12:30		Move to Well Rig up WL & PT Run in Hole w/ WL.
	1pm	& Perf 2" Tubing & 4½ csg.
1pm		Plug #1 Mix 28 sx cement & spot From 300' to Surface
		Cut 2" tubing off & Let it Drop. Then Weld on 4" collar
		Tie in to 4½ csg. Mix 15 sx & squeeze in Perf. at 300'
	2pm	Shut Well In w/ 250 PSI
2pm		Perf Well at 30' Pump 5 BBL at 100 PSI NO circulation
		Behind 4" csg. Mix Plug #3 15sx Pump in to Perf NO circulation
		Shut Well In Wash up Install marker
		move to SFP #23

Fuel & Motor Oil _____ Water Hauled _____

Rental Equipment ~~Per 1 Hole At 300' w~~ Cement Retainers _____

Cementing Plug #1 28 sy Plug 2 13 sy Plug #3

Wireline Perf 1 Hole at 300' w/ 1 1/16 Biwire shot Perf 1 Hole at 30' w/ 1 1/16 Biwire.