
Form 9-331 (May 1963)					5. LEASE DESIGNATION AND SERIAL NO. CONTRACT 417	
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)				6. IF INDIAN, ALLOTTEE OF TRIBE NAME  JI CARILLA		
1. OIL GAS WELL WEL	L XX OTHER	7. UNIT AGREEMENT NAME				
2. NAME OF OPERATO	R	8. FARM OR LEASE NAME				
				CHACON JICARILLA		
KEESEE & THOMAS  3. ADDRESS OF OPERATOR				9. WELL NO.		
P. O. BOX 2026, FARMINGTON, NEW MEXICO 87401				1		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*				10. FIELD AND POOL, OR WILDCAT		
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements See also space 17 below.) At surface 790' FSL, 790' FWL				BALLARD		
				11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA		
				15, T-23-N	N, R-3-W	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH 13. STATE		
14. PERMIT NO.		7383' GR.		RIO ARRIBA	N.M.	
16.	Check Ap	propriate Box To Indicate	e Nature of Notice, Report, or (	Other Data		
NOTICE OF INTENTION TO:				QUENT REPORT OF:		
TEST WATER SH FRACTURE TREAT SHOOT OR ACIDIZ REPAIR WELL (Other) RUN  17. DESCRIBE PROPOSE proposed work nent to this wo	UT-OFF  N  N  I PRODUCTIO  ED OR COMPLETED OFE  L. If well is directio	ULL OB ALTER CASING ULTIPLE COMPLETE BANDON* HANGE PLANS N CASING XX	WATER SHUT-OFF  FRACTURE TREATMENT SHOOTING ON ACIDIZING  (Other)  (NOTE: Report result Completion or Recomplinent details, and give pertinent dates locations and measured and true vertices.	REPAIRING OF ALTERING COMPANDED SOFT MULTIPLE COMPLETION REPORT and Log for a linear collection and log for all marker collections.	on Well	
IT IS IN	TENDED TO	RUN 99 JTS, 4½	", K-55, 9.5# CASIN	G TO 3268' AI	ND CEMENT	

WITH 100 SACKS C CEMENT.





TITLE

18. I hereby certify that the foregoing is true and correct

(This space for Federal or State office use)