UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

5. LEASE	
Federal NM	#28694
	TTEE OR TRIBE NAME

GEOLOGICAL SURVEY	6. IF INDIAN, ACCOUNTED ON THIS ENGINE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for shall pubposals.)	8. FARM OR LEASE NAME
4 11 700	Bad Lands
1. oil gas WK other	9. WELL NO.
2. NAME OF OPERATOR	#1
Jack A. Cole	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	South Blanco Extension
P. O. Box 191, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 9-T23N-RIW
below.) AT SURFACE: 1120' FSL 1850' FWL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same	Rio Arriba New Mexico
AT TOTAL DEPTH: Same	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
	7590' GL 7595' KB
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
FRACTURE TREAT SHOOT OR ACIDIZE	
REPAIR WELL	(NOTE: Report results of multiple completion or zone -change on Form 9–330.)
FULL OR ALTER CASING	change on Form 9–330.)
MULTIPLE COMPLETE	71994
CHANGE ZONES	
(other) See Below BUREAU OF ARMINGTON OF	was was a second of the second
Reserve pit has been covered up. Locat reseeded with BIA (Jicarilla) seed mix	ion and access road
	SEP 13 1984 L. C. DIST. 3
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct	,
SIGNED Daverpre Blancett TITLE Prod. Sup	ot. September 6, 1984
(This space for Federal or State	
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	ACCEPTED FOR RECORD
	1094
*See Instructions on Revers	No. P. L. Committee of the Committee of
	FARMINGTON RESUURCE AREA
	EARWINGTON KESOOMOS
	- 683
	BYG