



P. O. Box 1809
Durango, Colorado 81301

AIR MAIL

May 22, 1969

Mr. Keith L. Rising
P. O. Box 811
Lamar, Colorado 81052

Dear Mr. Rising:

Your letter of May 20, 1969, indicated you plan a trip to the area of your operations in T. 18 N., R. 3 W., Sandoval County, New Mexico, in the immediate future. While in the area, you are requested to see that the pits at your No. 3 Federal (Harvey) well, located in the NW $\frac{1}{4}$ SW $\frac{1}{4}$ sec. 21, T. 18 N., R. 3 W., on Federal lease N.M. 0558138, are filled and leveled and that a five-sack cement plug is placed in the surface casing of this abandoned well.

Following completion of this work, we will inspect the location, approve the abandonment, and notify the Bureau of Land Management that your operators bond may be terminated.

Sincerely yours,

(Orig. Sgd.) E. A. SCHMIDT

Edward A. Schmidt
Acting District Engineer

cc:
Roswell
NMOCC, Aztec, N. M. ✓
File