



P.O. Box 3038 • Farmington, New Mexico 87499

(505) 325-3404

David B. Tentler
Owner - Operator
Fax # (505) 326-7217

December 2, 1992

RECEIVED

DEC 2 8 1992

CON. DIV

MINERALS BRANCH	
BRANCH CHIEF	<i>[Signature]</i>
ASST. CHIEF	
PROD. MGR.	<i>[Signature]</i>
RES. MGR.	
ENV. MGR.	
INSPECTION	
LEGAL	
ADMIN.	
TRAINING	
SALES	

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
ATTN: STEVE MASON
1235 LA PLATA HIGHWAY
FARMINGTON NM 87401

RE: Jicarilla Contract 55A - Well #6
790' FSL & 790' FWL
SW $\frac{1}{4}$ SW $\frac{1}{4}$, Sec. 26, T23N, R3W
Sandoval County, NM

Dear Steve:

Relative to our recent telephone conversation on the above captioned matter, I am attaching to this letter a letter I wrote to El Paso Natural Gas on July 15, 1992, requesting a reconnection of the aforementioned well.

In the latter part of June 1992, Billco Energy did extensive reworking on this well, including but not limited to cleaning the well bore. The unprocessed natural gas pressures were favorable. We maintained a 225 pound casing pressure, along with a 225 pound tubing pressure. The maximum open flow tests accomplished on the well would indicate that the well is capable of producing 500 MCF a day. With a $\frac{1}{4}$ inch plate against a 190 pound line pressure, the well will be capable of producing 20 MCF a day. We feel that this is economically feasible to produce this well and have requested El Paso to reconnect the well, per the attached letter.

Steve, please let me know if there is anything else that needs to be accomplished. I will continue to pursue El Paso for a reconnect.

Thanks again, and make it a good day.

Sincerely yours,

David B. Tentler
Owner/Operator

Enclosure

[Handwritten initials]