Form 9-331 (May 1963)	UNITED STATES DEPARTMENT OF THE INT GEOLOGICAL SURVEY	Contract No. 55-A
SUN (Do not use this	DRY NOTICES AND REPORT form for proposals to drill or to deepen or p Use "APPLICATION FOR PERMIT—" for st	S ON WELLS lug back to a different reservoir. Jicarilla Apache Jicarilla Apache
1. OIL ▽ GAS	OTHER	7. UNIT AGREEMENT NAME
WELL WELL 2. NAME OF OPERATOR		8. FARM OR LEASE NAME. Chacon Jicarilla Apache
DAVE M. TH	IOMAS, JR.	9. WELL NO.
P. O. Box	2026 Farmington Report location clearly and in accordance with	N.M. 87401 any State regulrements.* 109 10. FIELD AND POOL, OR WILDCAT
See also space 17 belo At surface	ow.)	Chacon Dakota Associate
1830'FSL,	1830'FEL	Sec. 26-T23N-R3W
14. PERMIT NO.	15. ELEVATIONS (Show wheth	N.M.P.M. er df, rt, gr, etc.) 12. COUNTY OR PARISH 13. STATE
	7394'GL; 740	7'DF; 7408'KB Sandoval N.M.
16.	Check Appropriate Box To Indica	te Nature of Notice, Report, or Other Data
1	NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
TEST WATER SHUT-OF		WATER SHUT-OFF REPAIRING WELL FRACTURE TREATMENT X ALTERING CASING
FRACTURE TREAT SHOOT OR ACIDIZE	MULTIPLE COMPLETE ABANDON*	SHOOTING OR ACIDIZING ABANDONMENT*
REPAIR WELL	CHANGE PLANS	(Other) (Note: Report results of multiple completion on Well
(Other)		Completion or Recompletion Report and Log form.) tineut details, and give pertinent dates, including estimated date of starting any
See Attach	ned Fracture Treatments	RECEIVED AUG 2010G U. S. GEOLOGICAL SUPVEY FARMINGTON, 11 III.
FOR: DAVI		AUG291980 OIL CON. COM. President, Walsh Engineering 3 Production Corp. PATE 8/20/80

AUG 28 1980

*See Instructions on Reverse Side

FRACTURE TREATMENT

Formation Dakota "B" Stage	
Operator Dave M. Thomas,	Jr. Chacon Jicarilla Jr. Lease and Well Apache D-109
Correlation Log	Type GR-CCL From 6100 To 7516
Temporary Bridge Plug	Type None Set At
Perforations	7347'-7359' & 7362'-7369' 1 Per foot type 3 1/2" Glass Strip Jet
Pad	7,030 gallons. Additives 1% Kcl. 2 lbs. FR-20 per 1000 gallons. 1 gallon Frac Flo per 1000 gallons. 15 lbs. Adomite per 1000 gallons
Water	40,000 gallons. Additives 1% Kcl. 2 lbs. FR-20 per 1000 gallons. 15 lbs. Adomite per 1,000 gallons
Sand .	40,000 lbs. Size 40-60
Flush	5,500 gallons. Additives 1% Kcl. 2 lbs. FR-20 & gallon Frac Flo per 1000 gallons. 15 lbs. Adomite per 1000 gallons
Breakdown	2400 psig
Ave. Treating Pressure	
Max. Treating Pressure	psig
Ave. Injecton Rate	30.0 BPM
Hydraulic Horsepower	2059 ННР
Instantaneous SIP	psig
5 Minute SIP	1500 psig
10 Minute SIP	1480 psig
15 Minute SIP	1430 psig AUG291980
Ball Drops:	None Balls at Old CON COM. psig
	Balls at gallons psig
	Balls at gallons psig increas
Remarks:	——————— $Walsh$ engineering & production corp.

FRACTURE TREATMENT

Formation Dakota Stage	No. 2 Date 8/21/80 Chacon Jicarilla
Operator Dave M. Thomas, J	- 1 11-11-2-00
Correlation Log	Type From To
Temporary Bridge Plug	Type Halco Speed-E-Line Set At 7320
Perforations	7233-7294
	1 Per foot type 3 1/2" Glass Strip Jet
Pad	10,000 gallons. Additives 1 % Kcl. 2 lbs. FR-20 per 1000 gallons. 1 gallon Frac Flo per 1000 gallons. 15 lbs. Adomite per 1000 gallons.
Water	80,000 gallons. Additives 1% Kcl. 2 lbs. FR-20 per 1000 gallons. 15 lbs. Adomite per 1000 gallons
Sand .	80,000 lbs. Size 20-40
Flush	gallons. Additives 1% Kcl. 2 lbs. FR-20 & gallon Frac Flo per 1000 gallons. 15 lbs. Adomite per 1000 gallons.
,	
Breakdown	
Ave. Treating Pressure	
Max. Treating Pressure	3300 psig
Ave. Injecton Rate	BPM
Hydraulic Horsepower	HHP
Instantaneous SIP	psig
5 Minute SIP	1650 psig
10 Minute SIP	1610 psig
15 Minute SIP	
Ball Drops:	20 Balls at 40,000 gallons 120 psig
	increa 10 Balls at 60,000 gallons 40 psig
	Balls at gallons psig increa
Remarks:	
	Walsh engineering a production corp.