

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE
(Other instructions on reverse side)

Form approved
Budget Bureau No. 42-11124

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ <i>Any</i>	7. UNIT/AGREEMENT NAME <i>Gallo Canyon, Fed State, New Mex</i>
2. NAME OF OPERATOR <i>Gulf Oil Corporation</i>	8. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <i>P. O. Box 670, Hobbs, NM 88240</i>	9. FARM OR LEASE NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) <i>At surface</i> <i>1524' FNN + 1874' FEL</i>	10. WELL NO.
14. PERMIT NO.	11. FIELD AND POOL, OR WILDCAT <i>Wildcat</i>
15. ELEVATIONS (Show whether DF, RT, CR, etc.) <i>6954' BL</i>	12. SEC. T. R. M. OR N.E. AND SURVEY OR AREA <i>Sec. 26 T23N-R6W</i>
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data	13. COUNTY OR PARISH <i>Arizonal</i>
13. STATE <i>NM</i>	

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

POH of production sept. set CIBP @ 7396' test csg 500#-OK.
Displaced csg w/abandonment mud. Spot 35' cmt on CIBP up to 7361'. Spot the following plugs: 137' @ 6488' (30 cu ft), 100' @ 5378' (41 cu ft), 100' @ 2860' (41 cu ft), 100' @ 2035' (41 cu ft), 100' @ 1634' (41 cu ft), 100' @ 1384' (41 cu ft), 100' @ 555' (41 cu ft), 30' to surf (12 cu ft). Witnessed by Larry Pishy w/BHM. Set well marker, cleared location.
PAP 352-84

18. I hereby certify that the foregoing is true and correct

SIGNED *R. D. Pith*

TITLE

Area Engineer

DATE

3-27-84

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NMOCC

*See Instructions on Reverse Side