

Ross Federal 27 #24

N-27-20N-1W

COTTON PETRO. CORP.

F

30-043-20699

11-29-83

F. Loc. 470/S;1875/W

Elev. 7133 GL

Spd.

Comp.


TD

PB

Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. I. @
 Csg. Perf. Prod. Stim.

T Gas
R
A
N
S

BO/D Grav. 1st Del. Gas
 I.P. MCF/D After Hrs. SICP PSI After Days GOR 1st Del. Oil

TOPS	NITD ☒	Well Log	TEST DATA						
Ojo Alamo	C-103	Plat ☒	Schd.	PC	Q	PW	PD	D	Ref.No.
land	C-104	Electric Log							
Fruitland		C-122							
Pictured Cliffs	Ditr	Dfa							
Chacra	Datr	Dac							
Cliff House									
Menefee									
Point Lookout									
Mancos									
Gallup									
Greenhorn									
Dakota									
Entrada									
	Acres 40								

P
o
o
i

WC Gallup Co. S 27 T 20N R 1W U Oper. Cotton Petro. Corp. Lse. Ross Federal 27 No. 24

04 JUN 1984

CERTIFIED MAIL-RETURN RECEIPT REQUESTED

Cotton Petroleum Corporation
 3773 Cherry Creek Drive, North #750
 Denver, Colorado 80209

Gentlemen:

Reference is made to the following Applications for Permit to Drill (APD's).

- 1) ~~43-24 Ross Federal, NE1/4 section 34~~ *never got APD*
- 2) 42-28 Ross Federal, SE1/4 section 28
- 3) 24-27 Ross Federal, SE1/4 section 27
- 4) 32-27 Ross Federal, SW1/4 section 27

All in T. 20 N., R. 1 W., Sandoval County, New Mexico, lease New Mexico-14824. The subject APD's are hereby rescinded and returned due to the lease expiration on May 31, 1984.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 15 days, it will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, will result in an assessment.

Sincerely yours,

/s/ J. Stan McKee

Area Manager

ABANDONED LOCATION

Enclosure

cc:
 BLM, Rio Puerco
 RHOCC
 ADO (01537)
 Well file
 DRO 9-1

016:EBeecher:el:6-1-84

RECEIVED

JUN 05 1984

OIL CON. DIV.
 DIST. 3